

Woon Meng Motor Pte Ltd (Co.Reg.No:200603678M)

50 Bukit Batok Street 23,, #01-06 Midview Building
Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

INSURER: ERGO Insurance Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG22001666	Date of Loss:	12/07/2023
Vehicle Reg. No.:	SMY5012Y	Driveable?	
Driver Age/Info:	38 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KHOO QUEE SONG	Contact No:	+6582338855
Driver:	KHOO QUEE SONG		

Make/Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Vehicle Reg. Date:	13/07/2020
Vehicle Colour:	MAROON		
Engine No:	LEB7103278	Chassis No:	GP72002462
Odometer:	45932 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	22

Present Location: WOON MENG MOTOR PTE LTD (BUKIT BATOK)

COST OF CLAIMS

	Amount
Parts	8,644.90
Miscellaneous Items	40.00
Labour	2,500.00
Paintwork Labour	1,400.00
Towing	0.00
Gross Total (S\$)	12,584.90
+ GST 8.00% (S\$)	1,006.79
Nett Amount (S\$)	13,591.69

This claim is handled by: HENG SEW SOW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Tan Min 97495749
- wp, Not Authorise
Ex: \$1000
17/7/23 @ 3pm
P/P Resurvey before paint
tan min @ lkkauto.com

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Jul 2023)
Parts: N/A HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Woon Meng Motor Pte Ltd/SMY5012Y/14/07/2023 15:31
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	dev *150.00 F
2	2		*FRONT BUMPER RETAINER	0.00	RHX 0.00	LH de *24.00 F
3	2		*FRONT FOG LAMP GRILLE	0.00	RHX 0.00	? *56.00 F
4	1		*FRONT BUMPER LOWER CENTER GRILLE	0.00	0.00	de *70.00 F
5	2		*FRONT BUMPER LOWER SIDE GRILLE	0.00	0.00	? *56.00 F
6	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	bt *195.00 F
7	1		*FRONT CENTER GRILLE	0.00	0.00	cur *155.00 F
8	1		*EMBLEM	0.00	0.00	cur *25.00 F
9	1		*FRONT CENTER GRILLE TOP CHORME	0.00	0.00	cur *160.00 F
10	1		*FRONT SUPPORT PANEL	0.00	0.00	bt *390.00 F
11	1		*FRONT SUPPORT TOP GARNISH	0.00	0.00	de *45.00 F
12	2		*FRONT HEADLAMP	0.00	RHX 0.00	LH cur *900.00 F
13	1		*AIR DUCT	0.00	0.00	cur *48.00 F
14	1		*AIR HOSE	0.00	0.00	de *25.00 F
15	1		*FRONT RADIATOR	0.00	0.00	? *520.00 F
16	1		*FRONT AIR CON CONDENSOR	0.00	0.00	? *500.00 F
17	1		*FAN BLADE LH	0.00	0.00	? *60.00 F
18	1		*FRONT BLADE RH	0.00	0.00	? *45.00 F
19	1		*FAN MOTOR LH	0.00	0.00	? *210.00 F
20	1		*FAN MOTOR RH	0.00	0.00	? *210.00 F
21	1		*FAN COWLING LH	0.00	0.00	? *60.00 F
22	1		*FAN COWLING RH	0.00	0.00	? *85.00 F
23	2		*FRONT RAD SIDE GARNISH	0.00	RH?	LH de *80.00 F
24	1		*FRONT BONNET LOCK STIKLE	0.00	0.00	? *48.00 F
25	2		*SUPPORT TOP STOPPER	0.00	0.00	cur *20.00 F
26	1		*SPARE TANK	0.00	0.00	de *48.00 F
27	1		*BATTERY TRAY	0.00	0.00	cur *30.00 F
28	1		*BATTERY TOP BRACKET	0.00	0.00	bt *28.00 F
29	1		*FUEL BOX	0.00	0.00	cur *800.00 F
30	1		*AIR CLEANER BOX	0.00	0.00	? *140.00 F
31	1		*WHEEL HOUSE	0.00	0.00	bt *100.00 F
32	1		*FRONT FENDER LH	0.00	0.00	bt *180.00 F
33	1		*HYBRID	0.00	0.00	cur *50.00 F
34	1		*FRONT SIDE SKIRT LH	0.00	0.00	Ry *220.00 F
35	1		*FRONT FENDER INNER GARNISH LH	0.00	0.00	? *80.00 F
36	1		*FRONT WINDSCREEN GLASS	0.00	0.00	cur *950.00 F
37	1		*FRONT TOP MOULDING	0.00	0.00	cur *30.00 F
38	1		*FRONT LOWER MOULDING	0.00	0.00	cur *40.00 F
39	1		*FRONT BONNET	0.00	0.00	bt *450.00 F
40	1		*FRONT BONNET LOCK	0.00	0.00	bt *90.00 F
41	1		*FRONT BONNET INNER TRIM	0.00	0.00	cur *210.00 F
42	2		*FRONT BONNET HINGE	0.00	0.00	ht *70.00 F
43	1		*FRONT BONNRT FRONT RUBBER	0.00	0.00	de *26.00 F
44	1		*FRONT WIPER GARNISH	0.00	0.00	de *180.00 F

F=Franchise part.

Woon Meng Motor Pte Ltd/SMY5012Y/14/07/2023 15:31. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	BATTERY	de / -
2	1	COOLANT	net / -
3	1	FRONT ERP BRACKET	net / -
4	1	FRONT NUMBER PLATE	net / -
5	1	FRONT WINDSCREEN SEALANT	net / 40.00
Sub Total (S\$)			40.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO PUTTY & SPRAY PAINTING	New	1200 1,400.00
<u>Labour Items</u>			
2	TO REMOVE, REPLACE, REPAIR & INSTALL FRONT DAMAGED PARTS	New	1000 1,800.00
3	TO R & R CHASSIS CROSSMEMBER	New	200? 280.00
4	TO R & R FRONT RADIATOR	New	600? 120.00
5	TO R & R AIR CON SYSTEM. TOP UP AIR CON GAS	New	600 150.00
6	TO R & R FRONT WINDSCREEN GLASS	New	120 150.00
Gross Labour Cost (S\$)			3,900.00

Woon Meng Motor Pte Ltd/SMY5012Y/14/07/2023 15:31. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >