

ASS. REC. BY:

REF:

145B/230071971KV

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

PMN 7650A

Mtr Regn:

08, 19

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

c.c

1498

Colour

M-Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

124066

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMGK3850KS205528

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

TOTAL

Report Format:

Lump-Sum / B.I. (\$

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 14 / 07 / 2023

ESTIMATE COSTS OF REPAIR

Mr. Tay Guo Xiong Alvin

C/o 160 Sin Ming Drive

#05-09 Sin Ming Auto City

Singapore 575722

*Not Notified
Running Repair
5 days*

Dear Sir / Madam ,

Vehicle no. : SMN 7650 A - Honda Jazz 1.5 CVT
Accident date : 14 / 07 / 2023

Quantity	Descriptions	Amount (S\$)
1	1 pc rear bumper	\$ 592.70 ✓
2	1 pc n/s rear bumper side retainer	\$ 26.50 X
3	1 pc n/s rear bumper air duct	\$ 30.00 X
4	1 pc n/s rear fender	\$ 626.70 ✓
5	1 pc n/s fender inner shield	\$ 250.00 X
6	1 pc n/s rear door	\$ 798.80 X
7	1 pc n/s rear door rubber	\$ 77.10 X
8	1 pc n/s rocker panel garnish	\$ 373.90 X
9	1 pc n/s rear wheel hup bearing	\$ 287.50 ✓
10	1 pc n/s rear shock absorber	\$ 324.00 X
11	1 pc rear axle beam	\$ 938.60 X

Less 20 %

\$ 4,325.80

\$ 865.16

\$ 3,460.64

12	1 pc n/s rear wheel tyre	\$ 385.00 sn X
13	1 pc n/s rear wheel rim	\$ 600.00 sn 60sn
14	1 pc n/s rear quarter glass inner seal	\$ 60.00 sn 30sn
15	1 pc n/s rear quarter glass inner gum	\$ 60.00 sn 30sn

Balance B/FD

\$ 4,565.64

Labour charge
To putty and spray painting
Re-seal anti rust
To check, replace, repair wiring
To check wheel alignment
To transfer n/s rear door
Remove and refix n/s rear quarter glass
Remove and refix n/s rear undercarrige
Remove and refix cushion seat, garnish, carpet, etc

\$ 1,600.00 600
\$ 1,300.00 800
\$ 200.00 300
\$ 160.00 150
\$ 120.00 600
\$ 120.00 X
\$ 120.00 400
\$ 380.00 X
\$ 380.00 1000

\$ 8,945.64

PLUS 8 % GST

\$ 715.65

Total

\$ 9,661.29