

DETAILS

CE

MRM-SG Version: 1.0 (Last Synchronised: 14 Jul 2023)
144 HYUNDAI KONA OS EV (A) (Catalogue:Merimen Singapore 1.0)
Repairer's (Price-denominated Standard List)

Ding Auto Pte Ltd/SNL3860K/14/07/2023 17:24

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Items/values not in reference catalogue are prefixed with an asterisk *.

s on Parts

Part No.	Particulars	%Disc	%Depr	Amount	
	*FRONT BUMPER	Bu / mm 0.00	0.00	*600.00 F	✓
	*FRONT BUMPER LOWER GRILLE	Net 0.00	0.00	*480.00 F	✓
	*FRONT BUMPER REINFORCEMENT	R 0.00	0.00	*340.00 F	✗
✓	*FRONT BUMPER SPONGE	Sn 0.00	0.00	*125.00 F	✗
	*FRONT RADAR SENSOR	Sn 0.00	0.00	*650.00 F	✗
	*FRONT HEADLAMP LHS	Sn 0.00	0.00	*600.00 F	✗
	*FRONT BUMPER RETAINER LHS	Sn 0.00	0.00	*20.00 F	✗
	*FRONT BUMPER RETAINER RHS	Sn 0.00	0.00	*20.00 F	✗
✓	*RADIATOR TOP GARNISH	CM Sn 0.00	0.00	*60.00 F	✗
✓	*FRONT BUMPER EV CHARGING PORT ASSEMBLY	CM 0.00	0.00	*880.00 F	✓
	*FRONT NUMBER PLATE GARNISH	Net 0.00	0.00	*20.00 F	✓
✓	*FAN COWLING	Sn 0.00	0.00	*300.00 F	✗
✓	*RADIATOR	Ry Sn 0.00	0.00	*360.00 F	✓
✓	*CONDENSER	Ty Sn 0.00	0.00	*380.00 F	✓
	*FRONT SUPPORT PANEL	Sn 0.00	0.00	*680.00 F	✗
	*FRONT BUMPER STIFFNER	Sn 0.00	0.00	*125.00 F	✗
	*FRONT HEADLAMP BOTTOM TRIM LHS	Sn 0.00	0.00	*55.00 F	✗
	*FRONT BUMPER CENTRE INNER TRIM	Sn 0.00	0.00	*60.00 F	✗
✓	*ELETRIC VEHICLE CHARGER SOCKET ASSEMBLY	CM 0.00	0.00	*1,980.00 F	✓
✓	*RADIATOR FAN/AIR GUARD	Net Sn 0.00	0.00	*50.00 F	✗
	*REINFORCEMENT DUCT	Sn 0.00	0.00	*400.00 F	✗
Sub Total (\$\$)				8,185.00	
+ Margin on L,N Items 10.00% (\$\$)				818.50	
Total Parts (\$\$)				9,003.50	

Ding Auto Pte Ltd/SNL3860K/14/07/2023 17:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS