

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER:
CCPL

India International Insurance Pte Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	11/07/2023
Vehicle Reg. No.:	SHA807P	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	24/09/2019
Vehicle Colour:	YELLOW		
Engine No:	G4LEKU362986	Chassis No:	KMHC851CVLU178407
Odometer:	427745 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Remarks:	TEL: 62148355		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	1,579.84
Miscellaneous Items	11.00
Labour	780.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,370.84
+ GST 8.00% (\$\$)	189.67
Nett Amount (\$\$)	2,560.51

This claim is handled by: **MS. LOKE YY**

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 13 Jul 2023)

Parts: 192 **HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA807P/13/07/2023 09:15

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER <i>Repair</i>	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER CLIPS <i>m</i>	20.00	0.00	*22.00 FL
3	1		*REAR BUMPER CENTRE MOULDING ASSY <i>de</i>	20.00	0.00	*451.25 FL
4	1		*REAR BUMPER REINFORCEMENT <i>?</i>	20.00	0.00	*394.80 FL
5	1		*ANTENNA SMARTKEY <i>?</i>	20.00	0.00	*40.50 FL
6	1		*REAR BUMPER FOG LAMP <i>?</i>	20.00	0.00	*201.50 FL
7	1		*REAR BUMPER SIDE BRACKET LH <i>X</i>	20.00	0.00	*55.80 FL
8	1		*REAR BUMPER SIDE BRACKET RH <i>X</i>	20.00	0.00	*55.80 FL
9	1		*REAR NUMBER PLATE WITH TRIM COVER <i>ca</i>	0.00	0.00	*55.00 F
10	1		*REAR BUMPER REVERSE SENSOR <i>?</i>	0.00	0.00	*180.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,916.05
- List Item Discount on L Items (S\$)	336.21
Total Parts (S\$)	1,579.84

ComfortDelGro Engineering Pte Ltd/SHA807P/13/07/2023 09:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

o Qty Particulars

Amount

Miscellaneous Items

1 1 OD/TP Case (Insurer)

11.00

Sub Total (\$\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

New

350 ~~400.00~~

2 SPRAY PAINTING CHARGE

New

250 ~~300.00~~

3 REMOVE/REFIX REVERSE SENSOR

New

80 ~~80.00~~

Gross Labour Cost (\$\$)

780.00

ComfortDelGro Engineering Pte Ltd/SHA807P/13/07/2023 09:15. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Passer
Hp 9001268
3 days
4/8
17/07/23
Beg after
repair