

ASS. REC. BY:

REF:

U02/23007223/K_N

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: YQ 5724B

Policy No. _____


Claims No. M12D00132307

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 07 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: TRQ 5878 Yr Regn: 071 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: NIS Almera c.c. 1498

Colour: M. Gray A/C: Insured / Std / NI / NA

Sp. Reading: 96017 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: PN8BBA N17.TCB46109

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Nil 195/60R15

R: 7070

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mm

L/Bal. 9 mm

D.O.A. 14/7/23

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 18/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24/7 21 Lp 8 650d Cabin (red 6906.20, 51%)

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 3/8/23-typist

Days Of Repair: 7

Resurvey No. of Trip: _____

Survey Fee:

Transportation:
S + RS. \$

Fees

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format: TP

Lump Sum / L.B.: (\$ 6500

TOTAL



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

UMQ4FGAW

No. Pendaftaran : JRQ5878
No. ID : 700331655018
Nama Pemunya Berdaftar : MARICEL ICASIAM RODULLO
Alamat : NO 15 JALAN TIMOR 16 TAMAN TIMOR
81300 SKUDAI JOHOR

(37) 0167491615/
019-7279853
071

No. Chasis/No. Enjin : PN8BBAN17TCB46100 / HR15913145D
Buatan>Nama Model : NISSAN / ALMERA 1.5E AT
Keupayaan Enjin : 1498
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat : MOTOKAR / 2016
Tarikh Pendaftaran : 28/07/2016
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



LESEN KENDERAAN MOTOR

AKTA PENGANGKUTAN JALAN 1987 KAEDAH KENDERAAN MOTOR (PENDAFTARAN DAN PELESENAN) 1959

Sila baca maklumat di muka sebelah sebelum
melekatkan LKM ini di cermin kenderaan anda

2017
JRQ5878 **27 JUL**
0101041 OzsWq7g 28072016
VEL02008 090329 RENI
SEMENANJUNG
28072016 27072017
1498SP AB RM90.00
PERSENDIRIAN



LESEN KENDERAAN MOTOR
AKTA PENGANGKUTAN JALAN 1987 KAEDAH KENDERAAN
MOTOR (PENDAFTARAN DAN PELESENAN) 1959

34298300



1 of 3

Report No. T/20230714/2077

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/07/2023 16:13		Vide Report No.:		Station Diary No.: 51	
Informant's Particulars					
Name of Informant: MOHAMAD SHAH HAN BIN MOHD NORDIN			Address:		
ID Type / ID No.: PASSPORT / A57013694			Contact No.:		
Nationality: MALAYSIAN			Home/Office:		Mobile: 88927134
Email:					
Sex: Male	Age: 22	Date of Birth: 03/11/2000	Type of Informant: Driver		
Race: Indian			Language: English		
Occupation: Student			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 14/07/2023 15:00	Type of Location: Straight Road
Location: TAMPINES EXPRESSWAY				
Weather: Drizzling		Road Surface: Wet		
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRQ5878	Car				Slightly Damaged	1
YQ5724B	Lorry					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



SINGAPORE
POLICE FORCE



T/20230714/2077

2 of 3

Police Station Of Origin:
Punggol N.P.C
151 Punggol Central SINGAPORE 828727
Tel No: 1800-6049999

Report No. T/20230714/2077

CONTINUATION OF REPORT

Driver				
Name	MOHAMAD SHAH HAN BIN MOHD NORDIN		ID No.	A57013694
Related Vehicle	JRQ5878 (Car)		Contact No.	88927134
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Driver				
Name	KRISHNASAMY MANIKANDAN		ID No.	G2104429L
Related Vehicle	YQ5724B (Lorry)		Contact No.	82621631
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 14 July 2023 at about 3pm, I was driving my vehicle JRQ5878 along TPE highway towards Punggol Way exit on the second lane. The vehicle in front of my brake and I also followed and brake to a complete stop. However the lorry behind me did not manage to stop completely and collided onto the rear of my car. Subsequently, I got out of my vehicle and exchanged particulars with the lorry driver and settle the issues via our insurance company.

My car suffered minor damage as one side of the rear bumper came loose. I am no injured and no police came to attend the scene. That is all.



**SINGAPORE
POLICE FORCE**



T/20230714/2077

3 of 3

Police Station Of Origin:
Punggol N.P.C
151 Punggol Central SINGAPORE 828727
Tel No: 1800-6049999

Report No. T/20230714/2077

CONTINUATION OF REPORT

Signature of Officer Recording The Report:

F /

SGT 3 LAI TECK YONG

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIA /

SR STAFF SGT FAHKRUL RAZI BIN SUHAIME

Contact No.: 65470000

Signature Of Informant:

Date/Time:

14/07/2023 16:13

Classification Of Case:

NP168

RS Auto
AUTOEXCEL ENGINEERING PTE LTD
160, SIN MING DRIVE, SIN MING AUTOCITY # 06-15
SINGAPORE 575722

Not Withheld
11 Day @ 85000
Repair After Paint
7 days

Date : 17 Jul 2023

QUOTATION - THIRD PARTY CLAIM

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 14 Jul 2023

VEH. No : JRQ 5878 / NISSAN ALMERA

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : KURNIA INSURANCE

QTY	ITEM	AMOUNT	
-----	------	--------	--

	YOUR INSURE : YQ 5724 B		
1	BOOTLID <i>791.50</i>	\$ <i>R</i> 895.00	<i>✓</i>
1	BOOTLID LOCK	\$ <i>R</i> 323.00	<i>X</i>
1	BOOTLID OUTER GARNISH <i>281.10</i>	\$ <i>msm</i> 385.00	<i>✓</i>
1	BOOTLID CENTER LOGO	\$ <i>R</i> 68.00	<i>✓</i>
1	BOOTLID ALMERA EMBLEM	\$ <i>R</i> 65.00	<i>✓</i>
1	BOOTLID HINGE LH	\$ <i>R</i> 323.00	<i>X</i>
1	TAILLAMP LH <i>302.80</i>	\$ <i>msm</i> 589.00	<i>✓</i>
1	TAILLAMP SIDE CLIP LH	\$ <i>R</i> 20.00	<i>✓</i>
2	TAILLAMP LOWER BRACKETS	<i>msm</i> \$ <i>cm</i> 280.00	<i>2+</i>
1	REAR W/SCREEN MOULDING	\$ <i>R</i> 185.00	<i>X</i>
1	REAR FENDER LH <i>1083</i>	\$ <i>Bu</i> 1,285.00	<i>✓</i>
1	REAR FENDER UNDER DUST COVER LH <i>116.80</i>	\$ <i>msm</i> 280.00	<i>✓</i>
1	REAR FENDER INNER SIDE TRIM LH	\$ <i>cm</i> 488.00	<i>✓</i>
1	REAR BUMPER <i>685.20</i>	\$ <i>Bu</i> 785.00	<i>✓</i>
1	REAR BUMPER SPONGE	\$ <i>R</i> 166.00	<i>X</i>
2	REAR BUMPER SIDE RETAINERS	\$ <i>msm</i> 240.00	<i>✓</i>
2	REAR BUMPER BRACKETS	\$ <i>msm</i> 220.00	<i>X</i>
1	END PANEL <i>491.60</i>	\$ <i>Bu</i> 620.00	<i>✓</i>
1	END PANEL TOP GARNISH <i>142.80</i>	\$ <i>msm</i> 388.00	<i>✓</i>
1	END PANEL TOP LATCH	\$ <i>R</i> 78.00	<i>X</i>
1	SPARE TYRE PANEL	REPAIR	
1	SPARE TYRE TOP BOARD	\$ <i>R</i> 485.00	<i>X</i>
	TOTAL PARTS :	\$ 8,168.00	
	LESS 10%	\$ 816.80	
	TOTAL LIST PARTS :	\$ 7,351.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

<u>S/NETT</u>			
1SET	REVERSE SENSOR	\$ <i>1m</i> 300.00	X
2T	REAR W/SCREEN SEALANT	\$ <i>m</i> 120.00	405m
1	BOOTLID TOP SPOILER	\$ <i>m</i> 500.00	2
1	REAR BUMPER LOWER SKIRTING	\$ <i>CM</i> 1,400.00	8005m
10	REAR BUMPER CLIPS	\$ <i>m</i> 45.00	✓
1SET	REAR No.plate	\$ <i>1m</i> 60.00	X
S/N PARTS :		\$ 2,425.00	
TOTAL PARTS PRICE :		\$ 9,776.20	
AMOUNT BRING FORWARD :		\$ 9,776.20	
Labour to do cutting , welding, repair , replace , align adjust accident affected area		\$ 1,400.00	1100l
Remove refix rear w/screen		\$ 140.00	120l
To transfer tailgate parts to another tailgate		\$ 140.00	50l
Remove refix replace inner board, side board, floor board upholstery etc		\$ 250.00	100l
To do anti rust		\$ 120.00	90l
Replace sensor, check rear wiring system etc		\$ 180.00	20l
To do spray painting on accident area (inner & outer)		\$ 1,400.00	1000l
TOTAL LABOUR :		\$ 3,630.00	
GRAND TOTAL PARTS & LABOUR :		\$ 13,406.20	