

ASS. REC. BY:

REF:

U02/23007223/K

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MY

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

JRG 5878

Yr Regn:

07/16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS Almera

C.C.

1498

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

96017

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

PN8BBA N17.T CB 46109

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F: NII

195/60R15

R: TOYO

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

8

mm

L/Bal.

9

mm

L/Bal.

8

mm

D.O.A.

14/7/12

D.O.I.

18/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

), Fines

), Others

TOTAL

Add Fee:

: Site Insp (\$

: Interview (\$

Tech Invs (\$

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$)

AUTOEXCEL ENGINEERING PTE LTD
160, SIN MING DRIVE, SIN MING AUTOCITY # 06-15
SINGAPORE 575722

Not Withheld
L1 Day 8
Repair After Paint
7 days

Date : 17 Jul 2023

QUOTATION - THIRD PARTY CLAIM

AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 14 Jul 2023

VEH. No : JRQ 5878 / NISSAN ALMERA

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : KURNIA INSURANCE

QTY	ITEM	AMOUNT
-----	------	--------

	YOUR INSURE : YQ 5724 B		
1	BOOTLID	\$ <i>R</i> 895.00	✓
1	BOOTLID LOCK	\$ 323.00	✓
1	BOOTLID OUTER GARNISH	\$ 385.00	✓
1	BOOTLID CENTER LOGO	\$ <i>mu</i> 68.00	✓
1	BOOTLID ALMERA EMBLEM	\$ <i>mu</i> 65.00	✓
1	BOOTLID HINGE LH	\$ <i>R</i> 323.00	X
1	TAILLAMP LH	\$ <i>my cm</i> 589.00	✓
1	TAILLAMP SIDE CLIP LH	\$ <i>mu</i> 20.00	✓
2	TAILLAMP LOWER BRACKETS	\$ 280.00	✓
1	REAR W/SCREEN MOULDING	\$ <i>mu</i> 185.00	X
1	REAR FENDER LH	\$ <i>Bu</i> 1,285.00	✓
1	REAR FENDER UNDER DUST COVER LH	\$ <i>S</i> 280.00	✓
1	REAR FENDER INNER SIDE TRIM LH	\$ 488.00	✓
1	REAR BUMPER	\$ <i>Bu</i> 785.00	✓
1	REAR BUMPER SPONGE	\$ 166.00	✓
2	REAR BUMPER SIDE RETAINERS	\$ <i>MJum</i> 240.00	✓
2	REAR BUMPER BRACKETS	\$ <i>MS?</i> 220.00	✓
1	END PANEL	\$ 620.00	✓
1	END PANEL TOP GARNISH	\$ 388.00	✓
1	END PANEL TOP LATCH	\$ <i>R</i> 78.00	X
1	SPARE TYRE PANEL	REPAIR	
1	SPARE TYRE TOP BOARD	\$ <i>R</i> 485.00	X

TOTAL PARTS : \$ 8,168.00
LESS 10% \$ 816.80
TOTAL LIST PARTS : \$ 7,351.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

<u>S/NETT</u>			
1SET	REVERSE SENSOR	\$ <i>hm</i> 300.00	X
2T	REAR W/SCREEN SEALANT	\$ <i>hm</i> 120.00	4012
1	BOOTLID TOP SPOILER	\$ 500.00	7
1	REAR BUMPER LOWER SKIRTING	\$ <i>cm</i> 1,400.00	80012
10	REAR BUMPER CLIPS	\$ <i>hm</i> 45.00	✓
1SET	REAR No.plate	\$ <i>hm</i> 60.00	X
S/N PARTS :		\$ 2,425.00	
TOTAL PARTS PRICE :		\$ 9,776.20	
AMOUNT BRING FORWARD :		\$ 9,776.20	

Labour to do cutting , welding, repair , replace , align adjust accident affected area	\$ 1,400.00	?
Remove refix rear w/screen	\$ 140.00	1201
To transfer tailgate parts to another tailgate	\$ 140.00	501
Remove refix replace inner board, side board, floor board upholstery etc	\$ 250.00	1001
To do anti rust	\$ 120.00	?
Replace sensor, check rear wiring system etc	\$ 180.00	201
To do spray painting on accident area (inner & outer)	\$ 1,400.00	10001
TOTAL LABOUR :	\$ 3,630.00	
GRAND TOTAL PARTS & LABOUR :	\$ 13,406.20	



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

UMQ4FGAW

No. Pendaftaran : JRQ5878
No. ID : 700331655018
Nama Pemunya Berdaftar : MARICEL ICASIAM RODULLO
Alamat : NO 15 JALAN TIMOR 16 TAMAN TIMOR
81300 SKUDAI JOHOR

31 0167491615/
019-7279853
051


No. Chasis/No. Enjin : PN8BBAN17TCB46109 / HR15913145D
Buatan>Nama Model : NISSAN / ALMERA 1.5E AT
Keupayaan Enjin : 1498
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PERSENDIRIAN-MOTOKAR INDIVIDU
Jenis Badan/Tahun Dibuat : MOTOKAR / 2016
Tarikh Pendaftaran : 28/07/2016
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -



LESEN KENDERAAN MOTOR

AKTA PENGANGKUTAN JALAN 1987 KAEDAH KENDERAAN MOTOR (PENDAFTARAN DAN PELESENAN) 1959

baca maklumat di muka sebelah sebelum
ekalkan LKM ini di cermin kenderaan anda



LESEN KENDERAAN MOTOR
AKTA PENGANGKUTAN JALAN 1987 KAEDAH KENDERAAN
MOTOR (PENDAFTARAN DAN PELESENAN) 1959

34298300



SINGAPORE POLICE FORCE



T/20230714/2077

Police Station Of Origin:
Punggol N.P.C
151 Punggol Central SINGAPORE 828727
Tel No: 1800-6049999

1 of 3

Report No. T/20230714/2077

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/07/2023 16:13		Vide Report No.:		Station Diary No.: 51	
Informant's Particulars					
Name of Informant: MOHAMAD SHAH HAN BIN MOHD NORDIN			Address:		
ID Type / ID No.: PASSPORT / A57013694			Contact No.: Home/Office: Mobile: 88927134		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 22	Date of Birth: 03/11/2000	Type of Informant: Driver		
Race: Indian			Language: English		
Occupation: Student			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 14/07/2023 15:00	Type of Location: Straight Road
Location: TAMPINES EXPRESSWAY				
Weather: Drizzling		Road Surface: Wet		
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JRQ5878	Car				Slightly Damaged	1
YQ5724B	Lorry					0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA