

Optima Werkz Pte Ltd
10 Ang Mo Kio Industrial Park 2A, #01-05/06 AMK Autopoint
Singapore 568047
Tel: 6481 1522

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC22P00251000	Date of Loss:	15/07/2023
Vehicle Reg. No.:	SDV739P	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KAM CHEE PENG		
Make/Model:	HONDA CIVIC, 2.0 L (A)	Vehicle Reg. Date:	27/10/2011
Vehicle Colour:	WHITE	Chassis No:	JHMF02640AS200014
Engine No:	K20Z25500014		
Odometer:	195061 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5 ✓		
Present Location:	OPTIMA WERKZ PTE LTD (HQ)		

*Not Authorised
L1 Pump &
Pump After Pump
Ex 81000.*

COST OF CLAIMS

	Amount
Parts	4,885.10
Miscellaneous Items	230.00
Labour	1,800.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,915.10
+ GST 8.00% (S\$)	553.21
Nett Amount (S\$)	7,468.31

This claim is handled by: LING TING AN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

AIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 18 Jul 2023)
 Parts: 143 HONDA CIVIC 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SDV739P)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		Air-cond condenser	0.00	0.00	*415.00 F	✓
2	1		Bonnet	0.00	0.00	*330.00 F	X
3	1		Bonnet hinge LH	0.00	0.00	*35.00 F	X
4	1		Bonnet hinge RH	0.00	0.00	*35.00 F	X
5	1		Bonnet lock	0.00	0.00	*70.00 F	✓
6	1		Bumper bracket LH, front	0.00	0.00	*18.00 F	✓
7	1		Bumper bracket RH, front	0.00	0.00	*18.00 F	X
8	1		Bumper reinforcement, front	0.00	0.00	*200.00 F	✓
9	1		Bumper, front	0.00	0.00	*220.00 F	✓
10	1		Headlamp LH	0.00	0.00	*460.00 F	✓
11	1		Headlamp RH	0.00	0.00	*460.00 F	✓
12	1		Panel, front	0.00	0.00	*780.00 F	✓
13	1		Radiator	0.00	0.00	*350.00 F	?
14	2		Radiator fan blade	0.00	0.00	*140.00 F	?
15	1		Radiator fan guard	0.00	0.00	*100.00 F	?
16	2		Radiator fan motor	0.00	0.00	*280.00 F	?
17	1		Radiator grille	0.00	0.00	*370.00 F	✓
18	1		Radiator grille emblem	0.00	0.00	*20.00 F	✓
19	1		*SUPPORT PANEL TOP GARNISH	0.00	0.00	*60.00 F	X
20	1		*FRONT GRILLE OUTER GARNISH COVER	0.00	0.00	*80.00 F	✓

F=Franchise part.

Sub Total (\$\$) 4,441.00
 + Margin on L,N Items 10.00% (\$\$) 444.10
 Total Parts (\$\$) 4,885.10

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Miscellaneous Items	
1	FRONT BUMPER CLIPS
1	FRONT GRILLE CLIPS
1	FRONT NUMBER PLATE & HOLDER
1	RADIATOR COOLANT

Amount	
New	50.00
New	50.00
New	50.00
New	80.00
60.00	
Sub Total (\$)	
230.00	

Estimates on Labour
o Particulars

Labour Items		Lab.Type	Amount
LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST FRONT ACCIDENT AREAS & ETC.		New	800.00
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH & ETC.		New	800.00
TO REFILL AIRCON GAS & ETC.		New	80.00
TO CHECK WIRING & ELECTRICAL SYSTEM.		New	120.00
600			
600			
✓			
200			
Gross Labour Cost (\$)		1,800.00	

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS
< END OF ESTIMATES >