

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01 (Claims & Performance  
Management)  
Singapore 068897From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 19 Jul 2023

**Preliminary Advice**

Vehicle No	: SNF5484G	Accident Date	: 15/07/2023
Make	: MERCEDES-BENZ E200	Policy No.	: SP2005511921
Assignment Date	: 18/07/2023	Excess	: S\$600.00
Date of Inspection	: 18/8/2023	Est. Duration of Repair	: 6
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PL		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,232.73
Revised Amount	:S\$	15,369.15
Check Items (Estimated)	:S\$	1,955.43
Total	:S\$	17,324.58

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	306,000.00
COE / PARF Rebate	:S\$	139,174.00
Salvage Value	:S\$	
Margin for Repair	:S\$	166,826.00

**Remarks** ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. ( X ) Other comments : Part by part repair as repairer is agent workshop

Please note that the preliminary advise amount (Revised &amp; Check items) stated are subject to consistency check, part prices and labour cost .