



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SNF5484G

ALLIANZ INSURANCE SINGAPORE PTE. LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information
WIP No: 17317
Reg No/Reg Date: SNF5484G / 02/06/2022
Date In/Mileage: 0
Chassis No: WVA230802E0403223
Engine No: 26492030483343
Make/Model: MB/E 200 SEDAN
Colour/Trim: 025 595 Nautic Blue/ 048 804 Sienna Brow

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	17/07/2023/ 11:43	K0	301 / Kerlyn Ong

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

Z REQUEST Customer Request M BPN SUN POLICY NO/ACC DATE : SP200511921 // 15/07/2023 DRIVE IN/EXCESS : 17/07/2023 // \$600 DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				
A BPILAB STRAIGHTEN, REMOVE SUPPORT ASSY FROM FRAME IMPACT DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH				2850 / 3840.00
A BPIRES RESPRAY BONNET, FRONT BUMPER & RH/ FRONT FENDER				2400 / 3080.00
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT			0.10	380.00
A BPILAB TO REMOVE, REPLACE HEADLAMP WITH FOCUS. NETT				120.00
M FRONT BUMPER	1.00	1723.81	00.00	1723.81
M RH/ FRONT BUMPER LOWER GRILLE	1.00	86.07	00.00	86.07
M RH/ FRONT BUMPER LOWER GRILLE Moulding	1.00	72.66	00.00	72.66
M RH/ FRONT BUMPER BRACKET	1.00	18.35	00.00	18.35
M FRONT DISTANCE SENSOR	1.00	306.95	00.00	306.95
M DECOUPLING RING	1.00	6.72	00.00	6.72
M RH/ BASIC CARRIER FOR BUMPER	1.00	71.09	00.00	71.09
M BONNET	1.00	2588.73	00.00	2588.73
M BONNET MERCEDES STAR	1.00	122.48	00.00	122.48
M BONNET SPRING ELEMENT	2.00	45.86	00.00	91.72
M BONNET RETAINING HOOK	1.00	97.70	00.00	97.70
M RH/ FRONT FENDER	1.00	1162.73	00.00	1162.73
M RH/ HEADLAMP UNIT	1.00	3677.73	00.00	3677.73
M RH/ HEADLAMP UNIT CONTROL UNIT	1.00	785.35	00.00	785.35
M FRONT STIFFENING	1.00	1080.64	00.00	1080.64

THIS IS NOT AN OFFICIAL TAX INVOICE
Handwritten notes:
- 6 days
- 18/07/23
- EXCESS: 600
- Repair by paint

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Confirmed & accepted by

Kerlyn Ong Kai Li

DID : 6771 4420 HP : 9186 5113

Email : kerlyn.ong@cyclecarriage.com.sg

Authorized signatory and company stamp
Cycle & Carriage Industries Pte Ltd

Nett 19,232.73
8% GST on 19232.73 1538.62

Total Payable 20,771.35

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383