

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Accident Date : 02.05.2023

Not Authn
11 Pny &
Pehny After Paint
EX TRA

D22MCV0010588

Policy No:

06.07.2023

Date:

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

Panel-Beating and Insurance Claim.		ESTIMATE		
数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.	
Estimate Cost of Repair to "Nissan Cabstar" Reg. No. GBH501E				
1pc	Front Windscreen Glass	55.00	CM 550.00 —	
2pcs	Front Windscreen Glass Mouldings		Na 110.00 —	
1pc	Front Windscreen Pillar RH		R 780.00 —	
1pc	Front Windscreen Pillar Inner Garnish RH		CM 190.00 —	
1pc	Wiper Panel		650.00 7	
1pc	Wiper Panel Garnish		R 280.00 —	
1pc	Wiper Linkage		85.00 7	
1pc	Wiper Arm Cover		N 6.00 —	
1pc	Wiper Motor		280.00 7	
1pc	Wiper Motor Bracket		30.00 7	
1pc	Wiper Tank		R 80.00 X	
1pc	Wiper Tank Motor		A 65.00 X	
1pc	Front Panel		R 700.00 —	
1pc	Front Panel Badge Cabstar		Na 35.00 —	
1pc	Front Panel Insulation		95.00 7	
1pc	Grille		mi 210.00 —	
1pc	Grille Emblem		mi 45.00 —	
1pc	Front Grille Bracket		D 15.00 —	
1pc	Front Bumper		R 450.00 X	
1pc	Front Bumper Bracket		Na / R 250.00 —	
1pc	Front Wiper Garnish Top Weatherstrip	D 28.00 —		
2pcs	Headlamps	240.00	480.00 —	
1pc	Headlamp Lower Garnish RH		CM 50.00 —	
1pc	Front Corner Panel RH		R 210.00 —	
1pc	Front Wing Mirror RH		R 95.00 —	
1pc	Front Wing Mirror Bolt Cover RH		mi 13.00 —	
1pc	Front Wing Mirror Bracket		CM 120.00 —	
1pc	Front Wing Mirror Bracket Garnish Cover		mi 68.00 —	
1pc	Front Door RH		R 650.00 —	
1pc	Front Door Top Hinge		R 55.00 —	
1pc	Front Door Lower Hinge		R 55.00 —	
1pc	Front Door Inner Lock		N 100.00 —	
1pc	Front Door Arrestor		35.00 7	
1pc	Front Door Channel		mi 60.00 —	
1pc	Front Door Weatherstrip		85.00 7	
1pc	Front Door Rubber Strip Lower		R 18.00 X	
1pc	Front Door Pillar		Na 780.00 X	
1pc	Front Door Pillar Inner Panel		R 255.00 —	
1pc	Front Door Chassis Draught Beeding		Na 130.00 —	
C/F			8,193.00	

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

D22MCV0010588

Policy No:

06.07.2023

Date:

Accident Date : 02.05.2023

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Nissan Cabstar" Reg. No. GBH501E		B/F	8,193.00
1pc	Front Door Step Garnish		140.00 X
1pc	Front Door Arch Panel Inner Trim		55.00 X
1pc	Front Door Lower Air Vent		38.00 ?
1pc	Front Door Step Garnish Door Inner Arch Garnish		60.00 X
1pc	Front Door Arch Rubber Outer		60.00 X
1pc	Front Door Glass		350.00 ✓
1pc	Front Door Glass Outer Moulding		75.00 ✓
1pc	Front Door Glass Inner Moulding		50.00 ✓
1pc	Front Door Glass Regulator		80.00 ?
1pc	Front Door Glass Vertical Garnish		60.00 ?
1pc	Front Door Glass Channel		50.00 ✓
1pc	Front Door Trim Board		370.00 ✓
1pc	Front Floor Member Cross		270.00 X
1pc	Dashboard		1,050.00 ✓
1pc	Dashboard Bracket RH		75.00 ?
1pc	Dashboard Lower Knee Board RH		80.00 ✓
1pc	Dashboard Reinforcement		850.00 ?
1pc	Dashboard Instrument Meter Assy		750.00 ?
1pc	Dashboard Brake Fluid Inspection Cover		48.00 ✓
1pc	Dashboard Cup Tray RH		90.00 ?
1pc	Dashboard Instrument Outer Casing		390.00 ?
1pc	Dashboard Reinforcement Side Bracket RH		75.00 ?
1pc	Brake Master Pump		230.00 ?
1pc	Brake Master Pump Air Servo		1,050.00 ?
1pc	Brake Master Pump Bracket		110.00 ?
1pc	Brake Servo		650.00 ?
1pc	Interior Air Con Blower Assy		350.00 ?
1pc	Interior Air Con Evaporator Unit		1,050.00 ?
1pc	Air Cleaner Intake Duct		72.00 X
1pc	Intercooler		1,150.00 X
1pc	Radiator		500.00 ?
1pc	Aircon Evaporator		1,250.00 X
1pc	Aircon Blower		500.00 X
1pc	Aircon Control		450.00 ?
1pc	Aircon Condenser		650.00 X
Cost Plus 10%			21,271.00
			2,127.10
			23,398.10
		C/F	23,398.10

Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
 Tel: 6484 1626 (24Hrs) Fax: 6484 0465
 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Policy No: D22MCV0010588

Date: 06.07.2023

Accident Date : 02.05.2023

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Nissan Cabstar" Reg. No. GBH501E		
		B/F	23,398.10
	Front Windscreen Sealant		50.00 401n
	Front Windscreen Fastener		50.00 X
	Front Windscreen IU Bracket		24.00 ✓
	Front Number Plate		45.00 X
	Front Door Reg Label		46.00 251n
	To Conduct Electrical Check, Focus Headlamp		30.00 201
	To Dismantle / Refit Front Windscreen Glass		120.00 ✓
	To Dismantle / Replace Dashboard to Facilitate Repair		150.00 ✓
	To Dismantle / Replace Aircon Evaporator / Blower to Facilitate Repair		150.00 710d
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		120.00 }
	To Dismantle / Refit Roof Lining		70.00 ✓
	To Provide Transportation (Towing)		(Bill) 180.00 ?
	Labour Charge - Panel Beating, Repairing of Front Chassis, Cabin Floor Panel, Door "B" Pillar, Roof Panel etc. Cnt, Weld Front Panel, Door Pillar & Part Replacement		1,200.00 1100d
	To Spray Paint Affected Areas		950d 1,000.00
		Total :	<u>26,633.10</u>

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: