

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: India International Insurance Pte Ltd
6 Raffles Quay
#22-00
Singapore 048580

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Krishnan Bhuvaneswari

Date: 19 Jul 2023

Preliminary Advice

Vehicle No	: GBH501E	Accident Date	: 16/06/2023
Make	: NISSAN CABSTAR	Policy No.	: D22MCV0010588
Assignment Date	: 19/07/2023	Excess	: S\$0.00
Date of Inspection	: 18/07/2023	Est. Duration of Repair	: 14
Inspection At	: CHEW GOON MOTOR (AMK) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #01-15/16 & 17, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	26,633.10
Revised Amount	:S\$	10,973.30
Check Items (Estimated)	:S\$	9,043.80
Total	:S\$	20,017.10

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	58,000.00
COE / PARF Rebate	:S\$	18,911.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,089.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :The vehicle repair on lump sum repair.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.