



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Ref: CS/GAI23007260/Uny3e2 Date: 25/07/2023 Code: GAI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBK 7872Y	Veh. Inspected	GBC 6613C
Policy No.	MOMVC000009100-01-000	Coverage (\$)	0.00
Claim No.	CLMOMVC000004370	Excess (\$)	0.00
Assign From	JOCELYN TENG	Assign Date	18/07/2023
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTFHT02PX00116107	Colour	YELLOW
Odometer	281410 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15	AUSTONE	6 mm
L/H Front Tyre	195 R15	AUSTONE	6 mm
R/H Rear Tyre	195 R15	AUSTONE	6 mm
L/H Rear Tyre	195 R15	AUSTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/07/2023	Inspection Date	18/07/2023
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	