



SV AUTOWORKS PTE LTD
8 Kaki Bukit Avenue 4
#02-24 Premier@ Kaki Bukit
Singapore 415875

Attention To:

ERGO Insurance Pte. Ltd.
8 Temasek Boulevard #04-01
Suntec Tower Three
Singapore 038988

Vehicle Details

Make & Model : HONDA VEZEL
Chassis No : RU11102376
Registration No : SNJ 6076 Z

S/N	Description	Qty	Amount (S\$)
1	Bonnet		\$ bt 1,034.70
2	Bonnet lock		\$ bt 234.60
3	Bonnet insulator		\$ de 396.40
4	Bonnet hinge LH		\$ bt 89.10
5	Bonnet hinge RH		\$ bt 90.10
6	Bonnet rubber long		\$? 182.00
7	Bonnet rubber short LH		\$? 135.00
8	Bonnet rubber short RH		\$? 136.00
9	Front bumper		\$ de 1,050.00
10	Front bumper side retainer LH		\$ de 144.40
11	Front bumper side retainer RH		\$ X 145.40
12	Front bumper fog lamp LH		\$ de 456.70
13	Front bumper fog lamp garnish LH		\$ de 126.20
14	Front bumper fog lamp housing LH		\$ ce 34.20
15	Front bumper fog lamp RH		\$ X 456.70
16	Front bumper fog lamp garnish RH		\$ X 126.20
17	Front bumper fog lamp housing RH		\$ X 34.20
18	Front bumper lower diffuser		\$ de 485.60
19	Front bumper reinforcement		\$ bt 486.10
20	Front bumper reinforcement top garnish LH		\$ de 24.20
21	Front bumper reinforcement top garnish RH		\$ X 25.20
22	Front bumper tow cover		\$ dy 83.20
23	Front bumper lower centre grille		\$ de 198.60
24	Front bumper dust cover		\$ de 384.70
25	Front bumper lower rubber		\$? 381.70
26	Head lamp LH		\$ ce 2,145.90
27	Head lamp lower bracket LH		\$ dy 176.10
28	Head lamp RH		\$? 2,145.90
29	Head lamp lower bracket RH		\$? 176.10
30	Front grille		\$ ce 582.30
31	Front grille emblem logo		\$ dy 89.10
32	Front grille side bracket LH		\$ de 87.30

33	Front grille side bracket RH	\$? 87.30
34	Front grille base	\$ <i>cur</i> 412.60
35	Front grille moulding	\$ <i>cur</i> 368.10
36	Front grille support bracket	\$ <i>dis</i> 198.20
37	Front fender LH	\$ <i>bt</i> 756.10
38	Front fender inner shield LH	\$ <i>fn</i> 134.20
39	Front fender arch garnish LH	\$ <i>de</i> 128.90
40	Front fender inner panel LH	\$? 561.70
41	Front fender RH	\$ <i>bt</i> 756.10
42	Front fender inner shield RH	\$ x 134.20
43	Front fender arch garnish RH	\$ x 128.90
44	Wiper tank	\$? 256.80
45	Wiper tank motor	\$? 150.40
46	Wiper garnish centre	\$? 425.60
47	Wiper garnish side LH	\$? 159.60
48	Wiper garnish side RH	\$ x 160.60
49	Horn LH	\$ <i>cil</i> 168.80
50	Horn RH	\$ x 169.80
51	Front support panel - <i>photo</i>	\$ <i>bt</i> 898.10
52	Front support panel top garnish	\$? 185.10
53	Front support panel side duct LH	\$ <i>de</i> 84.60
54	Front support panel side duct RH	\$ x 85.60
55	Front air duct	\$? 186.90
56	Front flexible duct	\$? 175.50
57	Temperature sensor	\$? 268.60
58	Air cleaner box	\$? 482.10
59	Air condenser	\$? 852.20
60	Air condenser suction pipe	\$? 398.10
61	Air condenser discharge pipe	\$? 352.10
62	Air condenser fan motor	\$? 298.20
63	Air condenser fan blade	\$? 57.50
64	Radiator	\$? 987.80
65	Radiator top pipe	\$? 148.60
66	Radiator bottom pipe	\$? 159.30
67	Radiator fan motor	\$? 1,076.40
68	Radiator fan blade	\$? 323.10
69	Radiator fan cowling	\$? 431.20
70	Radiator spare tank	\$? 55.20
71	Manifold cover	\$? 477.60
72	Steering wheel	\$ <i>act</i> 1,159.60
73	Steering wheel coil	\$ <i>act</i> 654.00
74	Steering wheel air bag	\$ <i>act</i> 2,980.40
75	Dashboard	\$ <i>de</i> 2,548.20
76	Dashboard air bag	\$ <i>act</i> 286.70
77	Air bag sensor	\$ <i>act</i> 636.80
78	Air bag control unit	\$ <i>act</i> 2,658.10
79	Seat belt LH	\$ <i>act</i> 1,621.10
80	Seat belt buckle LH	\$? 336.20

81	Centre pillar inner bottom garnish LH	\$?	397.50
82	Seat belt RH	\$?	1,621.10
83	Seat belt buckle RH	\$?	336.20
84	Centre pillar inner bottom garnish RH	\$ X	397.50
85	Front shock absorber LH	\$?	430.10
86	Front lower arm LH	\$?	374.10
87	Front knuckle arm LH	\$?	394.10
88	Front knuckle arm ball joint LH	\$?	168.20
89	Front knuckle arm bearing LH	\$?	181.40
90	Front Stabilizer bar	\$?	188.60
91	Front Stabilizer bar link LH	\$?	65.10
92	Roof lining	\$ de	1,258.20
93	Roof air bag	\$ at	1,076.80

TOTAL LIST \$ 45,255.60
20% 9051.12
\$ 36,204.48

S/N	Special Nett	Qty	Amount (\$\$)
1	Battery		\$? 200.00
2	Bonnet insulator clips		\$ 200 50.00
3	Front bumper clips		\$ 300 50.00
4	Front bumper reinforcement top garnish clips		\$ X 50.00
5	Front bumper dust cover clips		\$ X 50.00
6	Front grille clips		\$ 200 50.00
7	Front fender inner shield clips		\$ 200 80.00
8	Front fender arch garnish clips		\$ 100 80.00
9	Front support panel top garnish clips		\$ 200 50.00
10	Front support panel side duct clips		\$ X 50.00
11	Radiator coolant		\$ 50 50.00
12	Air con gas		\$ 50 50.00
13	Centre pillar inner bottom garnish clips		\$ X 80.00
14	Front rim		\$? 800.00
15	Front tyre		\$ X 400.00
16	Front number plate		\$ 45 50.00
17	Front number plate holder		\$ 50.00

TOTAL SPECIAL NETT \$ 2,190.00

S/N	Labour	Qty	Amount (\$\$)
1	Labour		\$ 2,000.00
2	Spray paint		\$ 2,000.00
3	rewire		\$ 100.00
4	Anti rust		\$ 200.00
5	R&R radiator		\$ 200.00
6	R&R air con condenser		\$ 200.00
7	R&R roof lining		\$ 300.00
8	R&R dash board		\$ 300.00

9	R&R steering wheel		\$	300.00	X
10	R&R both fronts seat belt		\$	300.00	100
11	Alignment		\$	100.00	80
12	R&R front undercarriage		\$	300.00	150?
13	R&R front rim		\$	100.00	X
14	R&R front tyre		\$	100.00	X
15	Upholstery		\$	300.00	X
16	Reprogramme		\$	300.00	150?
17	Refocus the headlamp beam		\$	50.00	30
18	Refocus the fog lamp beam		\$	50.00	30

TOTAL LABOUR \$ 7,200.00

TOTAL REPAIR COST \$ 45,594.48

Taufik 92415749
 'WP' Not Authorise
 Ex: to be advise 10days
 4/9 Resurvey after repair
 To check repair limit
 Taufik e/llh auto.com
 Resurvey check item

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be **resurveyed and**
 is subject to final approval from **Insurance Company**

Acknowledged by Repairer

Signature:

Date: