

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)  
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.  
79 Robinson Road #09-01 (Claims & Performance  
Management)  
Singapore 068897

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: JANICE KOH

Date: 19 Jul 2023

**Preliminary Advice**

Vehicle No	: YP1232K	Accident Date	: 14/07/2023
Make	: ISUZU NQR75UK5A	Policy No.	: SP2005996409
Assignment Date	: 19/07/2023	Excess	: S\$0.00
Date of Inspection	: 19/07/2023	Est. Duration of Repair	: 6
Inspection At	: ANN JOO MOTOR PTE LTD (HQ) BLK 176 SIN MING DRIVE #02-17, SINGAPORE 575721 SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,053.66
Revised Amount	:S\$	5,102.31
Check Items (Estimated)	:S\$	3,394.55
Total	:S\$	8,496.86

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	39,000.00
COE / PARF Rebate	:S\$	1,261.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,739.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Kindly advise the company sticker decal RH with insured policy? The vehicle repair on lump sum basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.