

93

AG

SMRT Accident Vehicle Repair Estimates

SMRT Auton
60 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera


User ID

Section A - Accident Details

Registration Number	SHC4901M
Case Reference Number	TAX/07/23/2043
Registration Date	16/10/15
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ZULKEFLI BIN MAHFUD
Type of Accident	Side Swipe
Accident Date and Time	16/7/23 12:34 PM
Accident Reported Date and Time	17/7/23 9:50 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24118883
Special Instruction to ARC, if any	TP/LEFT PORTION / DROVE IN
Prepared Date and Time	17/7/23 1:34 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$0.00
Total Spray Cost	\$2,392.00	\$0.00
Total Spare Part Cost	\$5,578.43	\$0.00
Total Other Cost	\$1,310.00	\$0.00
TOTAL COST	\$10,294.43	\$0.00
Lump Sum Total	\$10,300.00	\$0.00
Number of Repair Days	8.0	4 days / 4/5
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	17/07/2023 1:48 PM	
Signature		* Repair - HP 90010068 18/07/23 / Resing after repair request for MV
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

 Date Generated
 User ID

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	\$1,014.00	600
Total Labour	\$1,014.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	\$378.00	200
TO RESPRAY VIEW MIRROR	\$220.00	60
TO RESPRAY ROCKER PANEL MOULDING	\$220.00	X
TO RESRAY REAR DOOR LH	\$378.00	200
TO RESPRAY REAR FENDER LH	\$378.00	200
TO RESPRAY REAR BUMPER	\$378.00	200
RESPRAY WHEEL CAP	\$220.00	X
TO RESPRAY RIM	\$220.00	X
Total Spray Painting & Panel Beating	\$2,392.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	X
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	X
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$200.00	60
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	60
TO TRANSFER DOOR MECHANISM	\$240.00	100
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	X
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	X
TO REPLACE SUNDRY PARTS	\$100.00	X
Total Other Costs	\$1,310.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		67002-47070	DOOR FRT/LH	1.00	\$1,359.30	25.00	\$1,019.47	Replace	St-
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	mu
		87940-47310	MIRROR ASSY, LH	1.00	\$1,399.60	10.00	\$1,259.64	Replace	SCA
		87945-74010	COVER, OUTER MIRROR, LH	1.00	\$142.30	25.00	\$106.73	Replace	Repair
		52159-47905	BUMPER REAR	1.00	\$478.90	25.00	\$359.17	Replace	Repair
		90467-07211	BUMPER CLIPS (10 PCS)	10.00	\$2.40	25.00	\$18.00	Replace	X
		52576-47020	BUMPER SIDE RETAINER RR/LH	1.00	\$108.70	25.00	\$81.53	Replace	X
		52592-47021	BUMPER SEAL, RR LH	1.00	\$101.80	25.00	\$76.35	Replace	X
		76088-47020	BUMPER LIP COVER RR/LH	1.00	\$93.90	25.00	\$70.43	Replace	X
		67004-47080	DOOR RR/LH	1.00	\$1,213.70	25.00	\$910.28	Replace	St-
		61602-47091	FENDER RR/LH	1.00	\$980.80	25.00	\$735.60	Replace	Repair
			STRIDES LOGO	1.00	\$7.80	0.00	\$7.80	Replace	mu
			STICKER DECAL 65558888	1.00	\$21.60	0.00	\$21.60	Replace	mu
		42611-47140	WHEEL DISC	1.00	\$1,978.60	25.00	\$1,483.95	Replace	X
			TYRE	1.00	\$126.74	0.00	\$126.74	Replace	X
		42450-47040	WHEEL HUB REAR	1.00	\$645.60	25.00	\$484.20	Replace	X

SMRT Accident Vehicle Repair Estimates

SMRT Auton
60 Woodland
FAX Number
Estimator Tel
Accident Rep

Date Genera

User ID

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Ap
		42602-47060	CAP SUB-ASSY, WHEEL	1.00	\$229.70	25.00	\$172.27	Replace	SR
		61404-47030	SILL MEMBER OUTER LH	1.00	\$592.20	25.00	\$444.15	Replace	X
Total					\$9,543.64		\$7,437.91		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Ch
Total									

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: