

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: HL Assurance Pte Ltd  
11 Keppel Road  
#11-01 ABI Plaza  
Singapore 089057From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Grace Ng Tian Ai

Date: 20 Jul 2023

**Preliminary Advice**

Vehicle No	: SMU4011C	Accident Date	: 16/07/2023
Make	: BMW 320I	Policy No.	: MP321337
Assignment Date	: 19/07/2023	Excess	: S\$775.00
Date of Inspection	: 19/07/2023	Est. Duration of Repair	: 7
Inspection At	: WAH HONG MOTORS & CREDIT PTE LTD (HQ) 38 TOH GUAN ROAD EAST, #01-57, ENTERPRISE HUB SINGAPORE 608581		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,810.35
Revised Amount	:S\$	7,834.70
Check Items (Estimated)	:S\$	4,851.00
Total	:S\$	12,685.70

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	26,000.00
COE / PARF Rebate	:S\$	24,658.00
Salvage Value	:S\$	
Margin for Repair	:S\$	1,342.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( X ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :