



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

HSBC LIFE (SINGAPORE) PTE LTD

Ref: CS3/HSB23007304/Tvp3m4

10 MARINA BOULEVARD #48-01 MARINA BAY
FINANCIAL CENTRE TOWER 2 SINGAPORE
018983

Date: 31/07/2023

ATTN: LOW GARNET

Code: HSB

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHC 2233X	Veh. Inspected	SLC 6810G
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S3M04O65	Excess (\$)	0.00
Assign From	LOW GARNET	Assign Date	19/07/2023

2. Vehicle Particulars & Condition


Make & Model	BMW 318I	c.c	1499
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBA8E36000NT89400	Colour	WHITE
Odometer	110060 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50R17	PIRELLI	6 mm
L/H Front Tyre	225/50R17	PIRELLI	6 mm
R/H Rear Tyre	225/50R17	PIRELLI	6 mm
L/H Rear Tyre	225/50R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.



5. General Information

Accident Date	13/07/2023	Inspect Date / Time	19/07/2023 (02:20 PM)
Survey held at	SG-27 AUTOWORKS PTE LTD 60 JALAN LAM HUAT, #05-27, CARROS CENTRE, SINGAPORE 737869		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**

Report Ref No. CS3/HSB23007304/Tvp3m4

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.