

ASS. REC. BY: Tajj

REF:

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD/TP/WS/TP RES/OD RES/EVA/INV/MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SMJ26326 Yr Regn: 2019, Feb
Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Toyota Sienna c.c. 1416
Colour: Brn A/C: Insured / Std / NI / NA
Sp. Reading: 54943 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MHFZ28430000062436
Gen. Cond: ☒ Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or _____
Brake: In order / Jammed / Leaked / Burnt or _____
Modl: ☒ NII / S/Rim / STD A/Rim or _____
Tyre Size: F: 195/50R16
R: 20

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value: \$42K
IDAC Accident Rpt Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS WP
Date: _____ Person Contacted: _____
Vehicle: IN / OUT Partner

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / TOYO or _____

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>19/7/23</u>

Survey held at Teamwork
Des. of Damages: Frt ☒ Rear / O/S / N/S / U/G / Rooftop or _____

The U/G / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

i) _____
Date/Time, File Return to?
2) _____

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:	
Transportation:	
\$ + RS \$	
Photos	
Others	
TOTAL	

Rep. Format: _____
Lump Sum / L.B. / F. _____



Pte Ltd

bizSAFE
S T A R

TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

ROC number : 201015366H

REPAIR PERFORMANCE INVOICE

Vehicle number	SMJ2632G
Make / Model	TOYOTA SIENTA
Chassis number	MHFZ28H3000062436
Accident date	14/7/23
Reference	2307-19

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS

1	REAR BUMPER	638.43	de
2	REAR BUMPER SIDE GARNISH	609.70	?
2	REAR BUMPER RETAINER	314.40	X
1	REAR BUMPER CENTRE GARNISH	499.98	de
1	REAR BUMPER CENTRE REFLECTOR	290.00	cut
1	TAILGATE	1731.47	bt
1	TAILGATE EMBLEM - LOGO	84.60	nei
1	TAILGATE EMBLEM - V	98.00	nei
1	TAILGATE RUBBER	381.40	?
1	TAILGATE LOCK	371.40	?
1	TAILGATE LOCK STRIKER	61.00	X
1	TAILGATE INNER TRIM	791.10	X
1	TAILGATE INNER PULL COVER	141.00	X
1	TAILGATE GLASS MOULDING	241.00	nei
1	KEYLESS SENSOR	79.20	?
1	END PANEL	788.20	?
1	END PANEL TOP GARNISH	374.25	?
2	REAR FENDER INNER TRIM BOARD	1377.48	X

8872.61

Less 25%

Subtotal 2218.15

PARTS REPLACEMENT - SPECIAL NETT ITEMS

1 SET	REAR BUMPER CLIP	30.00	nei
1 SET	TAILGATE INNER TRIM CLIP	50.00	X
1	TAILGATE GLASS SEALANT	120.00	4ae
1	END PANEL TOP GARNISH CLIP	30.00	?
1	JOINT SEALANT	120.00	40?
1 SET	REVERSE SENSOR	250.00	200nm

Subtotal 600.00

LABOUR AND MISCELLANEOUS CHARGES

1	CHECK WIRING AND LIGHTING SYSTEM	100.00	30
2	REMOVE TRIMS & GARNISHES TO FACILITATE REPAIR	150.00	60
3	REMOVE & REPLACE REVERSE SENSOR	150.00	30
4	REMOVE & REFIT TAILGATE GLASS	150.00	120
5	PANEL BEATING ON AFFECTED AREAS	1200.00	600
6	SPRAY PAINTING ON AFFECTED AREAS	1200.00	600
7	APPLY ANTI-RUST ON AFFECTED AREAS	150.00	30

Subtotal 3100.00

Granttotal 10354.46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495744
wp' 19/7/23 @ 1pm
2/3 Resurvey after repair
2 days
tanpin @ 1/1/2023