



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: EILEEN LEE

Ref: CS/INC23007310/Uny3e2

Date: 03/08/2023

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | FBP 7355Y      | Veh. Inspected | PC 9003C   |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | MT/1232541-001 | Excess (\$)    | 0.00       |
| Assign From  | NUR ANISAH     | Assign Date    | 19/07/2023 |

### 2. Vehicle Particulars & Condition

|              |                   |              |              |
|--------------|-------------------|--------------|--------------|
| Make & Model | VOLVO B7R (A)     | c.c          | 7146         |
| Engine No.   | HIDDEN            | Year of Reg. | 2017         |
| Chassis No.  | YV3R6R624HA185776 | Colour       | MULTI COLOUR |
| Odometer     | 317983 KM         | Steering     | IN ORDER     |
| Brakes       | IN ORDER          | Modification | NIL          |
| General      | GOOD              |              |              |

### 3. Conditions of Tyres

|                | Size             | Make    | Balance |
|----------------|------------------|---------|---------|
| R/H Front Tyre | 295/80 R22.5     | PIRELLI | 6 mm    |
| L/H Front Tyre | 295/80 R22.5     | PIRELLI | 6 mm    |
| R/H Rear Tyre  | 295/80 R22.5 (D) | PIRELLI | 6/6 mm  |
| L/H Rear Tyre  | 295/80 R22.5 (D) | PIRELLI | 6/6 mm  |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

|                |                                                                                                             |                     |                         |
|----------------|-------------------------------------------------------------------------------------------------------------|---------------------|-------------------------|
| Accident Date  | 15/07/2023                                                                                                  | Inspect Date / Time | 28/07/2023 ( 10:22 AM ) |
| Survey held at | BLUWEL AUTOMOTIVE SERVICE PL<br>BLK 1 KAKI BUKIT AVE 6<br>#01-28/53/55/56 (MAIN OFFICE)<br>SINGAPORE 417883 |                     |                         |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days