



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0690/2023/EQ
DATE : 24-Jul-23
WIP : 29684

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/7/2023

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS TAN SIOK HONG
ADDRESS : 11 BALMORAL ROAD
#09-09
SINGAPORE 259796
TELEPHONE : HP +65 88200099
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SJK 99 P**
MODEL CODE : AUDI Q3 1.5 TFSI S-TRONIC
MODEL YEAR : 25/10/2022
ENGINE NO : DFY 357602
CHASSIS NO : WAUZZZF37P1027068
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Jul-23
PLACE OF ACCIDENT : PIE NEAR TO AMK AVE 1 EXIT

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJK 99 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEMS AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES AND RENEW IF NECESSARY.	S/N \$ 400.00	
3	TO DISMANTLE AND REINSTALL FRONT BUMPER. TO RENEW RHS FRONT FENDER AND RHS FRONT DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	
4	TO RESPRAY RHS FRONT FENDER, RHS FRONT DOOR AND HINGES.	\$ 2,800.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 7,072.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJK 99 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	FRONT FENDER - RH	1	\$ 1,530.00	
2	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 39.00	
3	FRONT WHEEL HOUSING LINER - RH	1	\$ 281.00	
4	FRONT DOOR - RH	1	\$ 3,192.00	
5	FRONT DOOR OUTER SEAL - RH	1	\$ 196.00	
6	FRONT DOOR ATTACHMENT PARTS	1	\$ 173.00	
7	FRONT DOOR CATCH	1	\$ 141.00	
8	FRONT DOOR HINGE HALVES - RH LOWER	1	\$ 56.00	
9	FRONT DOOR HINGE HALVES - RH LOWER	1	\$ 56.00	
10	FRONT DOOR COVER - RH	1	\$ 299.00	
11	FRONT WHEEL COVER - LH / RH	2	\$ 598.00	
12	FRONT SILL PANEL SEAL - RH	1	\$ 159.00	
13	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 7,220.00	
TOTAL LABOUR CHARGES		:	\$ 7,072.00	
GRAND TOTAL		:	\$ 14,292.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT