

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 20 Jul 2023

Preliminary Advice

Vehicle No	: SDH8282K	Accident Date	: 15/07/2023
Make	: BMW 740I	Policy No.	: SP2003053272
Assignment Date	: 19/07/2023	Excess	: S\$0.00
Date of Inspection	: 19/07/2023	Est. Duration of Repair	: 6
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,910.15
Revised Amount	:S\$	13,465.10
Check Items (Estimated)	:S\$	16,590.05
Total	:S\$	30,055.15
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	85,580.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,420.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :The repairer willing to undertake the repair cost at \$22,000.00 on part by parts basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.