

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autocentre Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@ahlmnet.com.sg
GST:M9-0009639-E RCB NO:06470300E

SURVEYOR COPY

M/S : MITSUBISHI HC CAPITAL ASIA PACIFIC PTE LTD
111 SOMERSET RD #14-05
TRIPLEONE SOMERSET
SINGAPORE 238164

Estimate No: MC1903648
Date: 19 Jul 2023
Policy No: CN013767
Veh Reg No: SMW2414B
Make/Model: OPEL GRANDLAND X
F12XHT AT

ATTN:

Your Ref No: SMW2414B
Claim Type: Third Party → *longue*
Accident Date: 16/07/2023
TP Veh Reg No: GBL8777C

10-1030

*Not Authorized
Return B & Paint
4 days*

Estimate Repair Cost to Vehicle No :SMW2414B

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 SIDE MIRROR ASSY LH	1 PC	<i>ln</i> 1,188.00	X
2 SIDE MIRROR COVER LH	1 PC	<i>ln</i> 306.00	X
3 REAR DOOR LH	1 PC	<i>ln</i> 6,300.00	X
4 REAR DOOR LOWER GARNISH LH	1 PC	<i>ln</i> 540.00	X
5 REAR DOOR LOCK LH	1 PC	<i>ln</i> 720.00	X
6 REAR DOOR RUBBER (AT DOOR) LH	PC	<i>ln</i> 324.00	X
7 REAR FENDER COWLING LH <i>protect</i>	1 PC	<i>ln</i> 504.00	✓
8 REAR FENDER COWLING CLIPS	8 PC	<i>ln</i> 72.00	—
9 REAR BUMPER	1 PC	<i>ln</i> 2,700.00	X
10 REAR BUMPER CLIPS	8 PC	<i>ln</i> 72.00	X
11 REAR BUMPER SIDE RETAINER LH	1 PC	<i>ln</i> 324.00	X
12 REAR WHEEL BEARING + HUB LH	1 PC	684.00	?
13 SPORTS RIM LHR (R17)	1 PC	<i>ln</i> 1,530.00	✓
		14,940.00	
	Less 10%	1,494.00	13,446.00
Special Nett			
14 TYRE LHR - CHECK PRICE	1 PC	<i>ln</i> 0.00	X
		0.00	0.00
LABOUR			
15 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	151
16 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	601
17 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	<i>ln</i> 120.00	X
18 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	<i>ln</i> 180.00	X
19 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE.	1 PC	120.00	?
20 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	<i>ln</i> 60.00	X
21 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	<i>ln</i> 60.00	X
22 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR REAR FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	600.00	4001

Zila
Ah Lim Motor Company

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : MITSUBISHI HC CAPITAL ASIA PACIFIC PTE LTD
111 SOMERSET RD #14-05
TRIPLEONE SOMERSET
SINGAPORE 238164

Estimate No: **MAC1903648**
Date: **19 Jul 2023**
Policy No: **CN013767**
Veh Reg No: **SMW2414B**
Make/Model: **OPEL GRANDLAND X
F12XHT AT**

ATTN:

Your Ref No: **SMW2414B**
Claim Type: **Third Party**
Accident Date: **16/07/2023**
TP Veh Reg No: **GBL8777C**

Estimate Repair Cost to Vehicle No :SMW2414B

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
23 TO SPRAY SIDE MIRROR COVER LH, REAR DOOR LH, REAR FENDER LH, REAR BUMPER.	1 PC	800.00	600
		2,060.00	2,060.00
		Total	S\$ 15,506.00
		Add GST @ 8%	1,240.48
		Total Amount Payable	<u>S\$ 16,746.48</u>

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND SEVEN HUNDRED FORTY SIX AND CENTS FORTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY

Zila
Ah Lim Motor Company

AUTHORISED SIGNATURE

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: