

DF MOTOR PTE LTD (202108068G)

32 SIN MING DRIVE 01-331

Sin Ming Industrial

SINGAPORE 575706

TEL :6453 9903

Email: dfmotor33@hotmail.com

Kenneth
96910663

"NOT Authored

11 Aug @

Recovery After Park

Kenneth Hoyle/kkauto.com

ESTIMATED COST OF REPAIR

Estimated repair list for the accident motorcycle Yamaha Xmax Vehicle NO.FBS1862Z

S/No	Part No.	Description	Qty	Amount (SGD)
1)	1PA-F6246-10	END,GRIP <i>CH</i>	1.00	<i>Re</i> \$38.00 ✓
2)		STEERING COD	1.00	" \$180.00 ?
3)	B74-E4718-00	PROTECTOR,MUFFLER 1	1.00	<i>Re/LM</i> \$95.00 ✓
4)	B74-E5431-00	COVER,CRANKCASE 3	1.00	<i>Re</i> \$85.00 ✓
5)	B74-F1511-00	FRONT FENDER	1.00	" <i>Re</i> \$80.00 X
6)	B74-1513-00-P4	STAY, FENDER 1 <i>CH</i>	1.00	<i>CM</i> \$75.00 ✓
7)	B74-1514-00-P4	STAY,FENDER 2	1.00	<i>Re</i> \$75.00 X
8)	B74-F171L-00-P4	MOLE,SIDE COVER 3	1.00	<i>CM</i> \$65.00 ✓
9)	B74-F171M-00-P4	MOLE,SIDE COVER 4	1.00	<i>CM</i> \$65.00 ✓
10)	B74-F172A-00	PANEL 1 <i>CH</i>	1.00	<i>Re</i> \$65.00 ✓
11)	B74-F1731-00-P4	<i>Re</i> COVER,SIDE 3	1.00	" <i>Re</i> \$75.00 ✓
12)	B74-F1741-00-P4	<i>Re</i> COVER,SIDE 4	1.00	<i>Re</i> \$75.00 ✓
13)	B74-F3102-00	FRONT FORK ASSY (L.H)	1.00	\$395.00 ?
14)	B74-F3103-00	FRONT FORK ASSY (R.H)	1.00	\$395.00 ?
15)	B74-3340-00	UNDER BRAKET COMP.	1.00	" \$498.00 ?
16)	B74-F474W-00-P4	ASSIST,GRIP 2 <i>Re</i>	1.00	<i>Re</i> \$90.00 ✓
17)	B74-F6110-00	HANDLE COMP. <i>CH</i>	1.00	<i>Re</i> \$150.00 ✓
18)	B74-F6290-00	REAR VIEW MIRROR ASSY (RIGHT)	1.00	<i>Re</i> \$120.00 ✓
19)	B74-H2129-00	COVER,BATTERY	1.00	<i>Re</i> \$45.00 ✓
20)		FRONT SKRUR <i>1801</i>	4.00	<i>Re</i> \$35.00 ✓

DF MOTOR PTE LTD (202108068G)

32 SIN MING DRIVE 01-331

Sin Ming Industrial

SINGAPORE 575706

TEL :6453 9903

Email: dfmotor33@hotmail.com.sg

ESTIMATED COST OF REPAIR

Estimated repair list for the accident motorcycle Yamaha Xmax Vehicle NO:FBS1862Z

S/No	Part No.	Description	Qty	Amount (SGD)
21)	B74-F7311-00	STAND.SIDE	1.00	<i>R</i> \$68.00 <i>X</i>
22)	B74-F7481-00	BOARD,FOOTREST	1.00	<i>607</i> 607 \$85.00 <i>✓</i>
23)	B74-7488-00	BOARD,FOOTREST 2	1.00	<i>" 607</i> \$85.00 <i>✓</i>
24)	B74-F8351-00-P4	BODY,COWLING	1.00	\$85.00 <i>?</i>
25)	B74-F835J-00-P2	BODY,FRONT UNDER 1	1.00	<i>" 607</i> \$90.00 <i>✓</i>
26)	B74-F835K-00-P2	BOBY,FRONT COVER 2 <i>114</i>	1.00	\$90.00 <i>?</i>
27)	B74-F8385-01	COVER,UNDER	1.00	\$80.00 <i>?</i>
28)	B74-F842A-00	COVER 5	1.00	\$45.00 <i>?</i>
29)	B74-F843C-00	COVER 6	1.00	\$48.00 <i>?</i>
30)	B74-H3310-00	FRONT FLAHER <i>Plash</i> LIGHT ASSY 1	1.00	<i>607</i> \$75.00 <i>✓</i>
31)	B74-H3912-00	LEVER 1	1.00	<i>R</i> \$38.00 <i>✓</i>
32)	B74-H4300-00	HEADLIGHT ASSY	1.00	<i>607</i> \$595.00 <i>✓</i>
33)	B74-F7111-00	STAND MAIN <i>103</i>	1.00	<i>" R</i> \$118.00 <i>✓</i>
33)	LABOUR			\$550.00 <i>2801</i>

TOTAL: \$ 4753.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: