

ASS. REC. BY:

REF:

AGL 23007342/Kny3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMH 90032 Yr Regn: 02, 19Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Vios E c.c. 1496Colour: Black A/C: Insured / Std / NI / NASp. Reading: 73020 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NR 2B23F 3601163843Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15
R: _____BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO orContinental

Front

Rear

R/Bal. 7 mmR/Bal. 6 mmL/Bal. 7 mmL/Bal. 6 mmD.O.A. 14/7/23D.O.A. 20/7/2023

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear o/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/7 / 1 Simp 81100k Cahr (Red. \$ 6535, 85%)

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE #05-68 S737896

HP: 98888885

Not at home
11/11/2023 @ 1100h
Returning After Repair
3 days

Estimation

Date:

20/7/2023

Vehicle:

SMH9003L

Make / Model:

TOYOTA VIOS

Chassis No:

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	BOOTLID	1	\$ 659.00	\$ 659.00
2	BOOTLID TOP LOCK	1	\$ 214.00	\$ 214.00
3	BOOTLID LOGO	1	\$ 58.00	\$ 58.00
4	BOOTLID WEMBLEM 'VIOS'	1	\$ 62.00	\$ 62.00
5	BOOTLID EMBLEM 'E'	1	\$ 22.00	\$ 22.00
6	REAR BUMPER	1	\$ 591.00	\$ 591.00
7	REAR BUMPER TOW COVER	1	\$ 38.00	\$ 38.00
8	REAR BUMPER SIDE RETAINER (FRONT)	2	\$ 98.00	\$ 196.00
9	REAR BUMPER SIDE RETAINER (REAR)	1	\$ 55.00	\$ 110.00
10	REAR BUMPER REINFORCEMENT	1	\$ 398.00	\$ 398.00
12	REAR END PANEL	1	\$ 548.00	\$ 548.00
13	REAR END PANEL TOP GARNISH	1	\$ 229.00	\$ 229.00
14	REAR FLOOR PANEL TOP BOARD	1	\$ 135.00	\$ 135.00
LKK Auto Consultants hence notify the Repairer of the following:				\$ 3,260.00
Less 25%				\$ 815.00
Total				\$ 2,445.00

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

S/Nett items:				
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP	1	\$ 30.00	\$ 30.00
3	REVERSE SENSOR	1	\$ 200.00	\$ 200.00
				\$ 2,860.00
Labour to: REAR				
1	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 600.00	\$ 600.00
2	PANEL BEATING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
3	RESET TROUBLE CODE	1	\$ 300.00	\$ 300.00
4	REMOVE AND REFIT REAR UPHOLSTERY	1	\$ 200.00	\$ 200.00
5	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
6	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
7	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
				\$ 2,330.00
Parts Replacement Amount			\$ 5,305.00	
Total Amount for Labour			\$ 2,330.00	
Total Amount			\$ 7,635.00	