

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhammad Afiq Bin Mohamed Kamal

Date: 26 Jul 2023

Preliminary Advice

Vehicle No	: SNF5616T	Accident Date	: 17/07/2023
Make	: TOYOTA ALPHARD	Policy No.	: MPC23P00122100
Assignment Date	: 20/07/2023	Excess	: S\$0.00
Date of Inspection	: 25/07/2023	Est. Duration of Repair	: 5
Inspection At	: VERVE MOTORCLINIC PTE LTD (KAKI BUKIT) NO. 25 KAKI BUKIT ROAD 4, #03-39 SYNERGY@KB SINGAPORE 417800		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,281.00
Revised Amount	:S\$	6,984.50
Check Items (Estimated)	:S\$	990.00
Total	:S\$	7,974.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	290,000.00
COE / PARF Rebate	:S\$	126,062.00
Salvage Value	:S\$	
Margin for Repair	:S\$	163,938.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The vehicle repair on part by part basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.