

Acc. PLO. BY:

REF:

CS/ICS 23007344/Dy 3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: _____
at Workshop mis _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bel. or Market Value: _____
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repair: 5 days Res.: Yes or No
Lum Sum: 7/P % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SNF 5616T Yr Regr: June 2022
Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Toyota Alphard cc 2493
Colour: Black A/C: Insured / Std / NI / NA
Sp. Reading: 15317 T/Radio: Insured / Std / NI / NA
Eng/No: 2AR2782035
C/No: AYH300144531
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/60 R17
R: 11
BS / DUN / EXNOVA / GY / FS / LZA / MEC / OHTSU / PIR / SUMI /
TOYO / YOKO or Yokohama
Front: _____ Rear: _____
R/Bal: S' mm R/Bal: S' mm
L/Bal: S' mm L/Bal: S' mm
D.O.A: 17/07/2023 D.O.I: 25/07/2023
Survey held at: Verve Motor Kela Kulit.
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear.
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action / Instruction
	<u>BLICS OD</u>
	<u>MV 29010</u>
	<u>LTA 126K</u>
	<u>HL 164K</u>

Date/Time, File Pass to? ☐ : Prel. Report
1) ☐ : Final Report

Date/Time, File Return to? _____
2) _____

Report Forward: _____
I am a Police Officer

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Inve (\$)

Survey Fee:	
Transportation:	
S + RS \$	
Photos	
Others	

Verve Motorclinic Pte Ltd (Co.Reg.No:201800568H)

No. 25 Kaki Bukit Road 4, #03-39 Synergy@KB

Singapore 417800

Tel: 67022990 Email: jaronranz92@gmail.com

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type: OD (OWN DAMAGE)
Policy No: MPC23P00122100
Vehicle Reg. No.: **SNF5616T**
Driver Age/Info:
TP Injury Involved? NO
Insured/Claimant: WANG ZHIQIANG

Ref. No:
Date of Loss: 17/07/2023
Driveable?
Party At Fault: UNKNOWN
Third Party Involved? YES

Make/Model: TOYOTA ALPHARD, 2.4 (A)
Vehicle Colour: BLACK
Engine No: 2AR2782035
Odometer: 12345 KM

Vehicle Reg. Date: 03/06/2022
Chassis No: AYH300144531

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) 5

Present Location: VERVE MOTORCLINIC PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	9,801.00
Miscellaneous Items	50.00
Labour	2,430.00
Paintwork Labour	0.00
Towing	0.00

Nett Amount (S\$) **12,281.00**

This claim is handled by: JARON RANZ

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Jul 2023)
Parts: M1-MPV TOYOTA ALPHARD 2.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Verve Motorclinic Pte Ltd/SNF5616T/19/07/2023 15:15
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET <i>Dented</i>	0.00	0.00	*380.00 F ✓
2	1		*BONNET CHROME MOULDING <i>broken</i>	0.00	0.00	*200.00 F ✓
3	2		*BONNET HINGE RH/LH <i>H/S bt o/s ?</i>	0.00	0.00	*80.00 F
4	1		*BONNET LOCK <i>key</i>	0.00	0.00	*85.00 F X
5	1		*HEADLAMP LH <i>mainly broken</i>	0.00	0.00	*3,125.00 F ✓
6	1		*FRT GRILLE ASSY <i>arcade</i>	0.00	0.00	*950.00 F ✓
7	1		*FRT GRILLE EMBLEM LOGO <i>SVL</i>	0.00	0.00	*600.00 F X
8	1		*FRT BUMPER <i>distorted</i>	0.00	0.00	*450.00 F ✓
9	1		*FRT BUMPER SIDE CHROME LH <i>HH</i>	0.00	0.00	*120.00 F X
10	1		*FRT BUMPER FOG LAMP LH <i>HH</i>	0.00	0.00	*140.00 F X
11	1		*FRT BUMPER FOG LAMP GARNISH LH <i>HH</i>	0.00	0.00	*165.00 F X
12	2		*FRT BUMPER TOW COVER RH/LH <i>HH</i>	0.00	0.00	*100.00 F X
13	1		*FRT BUMPER GRILLE ?	0.00	0.00	*120.00 F ?
14	1		*FRT BUMPER ULTRASONIC SENSOR LH <i>HH</i>	0.00	0.00	*215.00 F X
15	2		*FRT BUMPER RETAINER RH/LH <i>HH</i>	0.00	0.00	*140.00 F X
16	1		*FRT BUMPER ABSORBER ?	0.00	0.00	*60.00 F ?
17	1		*FRT BUMPER REINFORCEMENT ?	0.00	0.00	*210.00 F ?
18	1		*FRT SUPPORT TOP CENTRE ASSY ?	0.00	0.00	*270.00 F ?
19	1		*FRT SUPPORT SIDE ASSY <i>key</i>	0.00	0.00	*180.00 F X
20	1		*FRT SUPPORT BRACE PANEL <i>HH</i>	0.00	0.00	*60.00 F Y
21	1		*A/C CONDENSER <i>HH</i>	0.00	0.00	*750.00 F X
22	1		*FRT FENDER LH <i>key</i>	0.00	0.00	*510.00 F X

F=Franchise part.

Sub Total (S\$)	8,910.00
+ Margin on L,N Items 10.00% (S\$)	891.00
Total Parts (S\$)	9,801.00

Verve Motorclinic Pte Ltd/SNF5616T/19/07/2023 15:15. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1 1 FRT NO PLATE *Grade*

35/- 50.00

Sub Total (\$\$) 50.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 TO CHECK ELECTRICAL SYSTEM AND FOCUS HEADLAMP

New *30/-* 60.00

2 TO REMOVE /REPLACE AND/OR TRANSFER ULTRASONIC SENSORS TO NEW BUMPER

New *60/-* 150.00

3 TO REMOVE, REINSTALL RADIATOR, A/C CONDENSER AND PIPINGS FOR NECESSARY REPAIRS

New 220.00 ?

4 TO REPAIR AFFECTED AREA AND REPLACE DAMAGED PARTS

New *600/-* 1,000.00

5 TO SPRAY PAINT ON AFFECTED AREA

New *600/-* 1,000.00

Gross Labour Cost (\$\$) 2,430.00

Verve Motorclinic Pte Ltd/SNF5616T/19/07/2023 15:15. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

24/07/2023 e1600w

Not Author

? / Part.

5 days.

Exuss IBA.

2Kk Auto