

FIRST AUTOWORKS

Repair Estimate

Date : 19/07/2023

Reference: SKU 2164G

Make: OPEL
Grandland

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SKU 2164G
CHASSIS NO.: W0VZRHNS6L6024672
ENGINE NO.: 10TMA30044272

Name of insured .: DARSHAN SINGH S/O JANG SINGH
Date of accident.: 20/06/2023

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

<u>No.</u>	<u>Qty</u>	<u>Part Description</u>	<u>Price (SGD)</u>
<u>1</u>	1	RR FENDER WHEELARCH GARNISH LH	240.00
<u>2</u>	1	REAR BUMPER LH	550.00
Parts Total:			790.00
Less 10%:			79.00
Total :			711.00


Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	1300.00
<u>2</u>	Carry out spray painting on accident affected area. (Rear bumper,)	1100.00
<u>3</u>	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	80.00
Labour Total :		2,480.00

Total : \$3,191.00
Gst (8%) : \$255.28
GRAND TOTAL: \$3,446.28

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully


Service Advisor
Ronnie Tan
DID: 6844 1985 Fax: 6844 5185