



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896

HP: 98888885

Estimation

Date:

20/7/2023

Vehicle:

SNK1093B

Make / Model:

TOYOTA PRIUS

Chassis No:

CHINA TAIPING

Not Notarise
Runny After Rain
1 day
8260k

No.	Description	Unit	Unit Price	Amount	
	Parts Replacement:				
1	REAR BUMPER	1	\$ 798.00	\$ ¹ 798.00	X
2	REAR BUMPER LOWER LIP	1	\$ 698.00	\$ ¹ 698.00	X
	TOTAL PART			\$ 7,595.00	
	LIST DOWN	25%		\$ 1,898.75	
	AFTER LIST DOWN			\$ 5,696.25	
	SPEICAL NETT				
1	REAR BUMPER CLIPS SET	1	\$ 50.00	\$ ⁱⁿ 50.00	X
2	REAR WHEEL SPORTS RIM RH	1	\$ 800.00	\$ ⁱⁿ 800.00	X
	TOTAL AMOUNT			\$ 1,000.00	
	LABOUR				
1	CHECK WIRING	~ 1	\$ 100.00	\$ 100.00	X
2	REMOVE AND REPAIR REAR UPHOLSTERY AND SEAT	~ 1	\$ 300.00	\$ 200.00	X
3	PANEL BEAT EFFECTED AREAS	1	\$ 300.00	\$ 300.00	600
4	REPAIR EFFECTED AREAS	1	\$ 300.00	\$ 300.00	2000
	TOTAL AMOUNT			\$ 900.00	
	Parts Replacement Amount			\$ 6,696.25	
	Total Amount for Labour			\$ 2,720.00	
	Total Amount			\$ 9,416.25	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: