

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S2M03ST4 Date: 27th July 2023

Our Ref: CS3/ASM22001170/Dqy3e2-1

M/s HSBC Life (Singapore) Pte Ltd

10 Marina Boulevard #48-01 Marina Bay Financial Centre Tower 2 Singapore 018983 (The Motor Claims Department)

Attn: Oh Vale

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMM 4287R INSURED VEHICLE: SH 6804R

ACCIDENT DATE: 05/02/2022

We thank you for your instruction on 20/07/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMM 4287R from M/s Impact Analysis Consulting Pte Ltd.
- b) Singapore Accident Statement of Vehicles SMM 4287R and SH 6804R.
- c) Police Report of Vehicles SMM 4287R
- d) Final Repair Bill of SMM 4287R from M/s Garage 13 Pte Ltd.
- e) Colour damaged vehicle photographs of SMM 4287R.

Pre-Repair Inspection Date: 08/02/2022 at M/s Garage 13 Pte Ltd, 8 Kaki Bukit Ave 4 #03-46 Premier, Singapore 415875.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SMM 4287R

Make & Model : Mercedes Benz C180 Avantgarde (R17 LED)

Year of Registration : 2017

Chassis Number : WDD2050402R262333

Engine Capacity : 1595 cc

- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.