

Not Notified

Date: 19/07/2023
Vehicle No: SNC8711Y
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA7MC385207-2021
Reg.Year: 2021

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SNC54M
Date of Accident: 28/05/2023
Estimator: TING AN
Surveyor:

1 day

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>n</i> \$1,214.95
SUB TOTAL				\$1,214.95
LESS 10%				-\$121.50
PARTS TOTAL				\$1,093.46

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>n</i> \$50.00
S/N TOTAL				\$50.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST FRONT ACCIDENT AREAS & ETC.

nn \$250.00 X

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER & ETC.

\$250.00 *2201*

TO CHECK WIRING & ELECTRICAL SYSTEM.

nn \$80.00 X

LABOUR TOTAL \$580.00

TOTAL \$1,723.46

TING AN

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: