

VERON

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors/ Adjusters Cargo Surveyors & Licensed Appraisers

227 Simei St 4 #06-42 Singapore 520227 Fax: 64444886 Company Registration No. 53139926E

**AUTOMOBILE INSPECTION REPORT****To:****TAY HWA SENG****C/O Block 1001 Bukit Merah Lane 3
#01-55 / #01 - 85 Singapore 159718****INSURANCE DETAILS**

Insured : -
 Policy No. / Claim No. : -
 Sum Insured : -
 Excess Clause : -
 Windscreen Coverage : -
 Type of Claims : Third Party Claims
 Third Party Insurer : -
 Third Party Policy No. : -

REFERENCE

Assigned By : As above
 Accident Date : 21 May 2023
 Assignment Date : 01 June 2023
 Inspection Date : 01 June 2023
 Our Reference No. : PAS/HSHW/230152/TP

Inspection Report Date : 12 June 2023**Workshop Name :****Hong San Hong Wei Pte Ltd****Inspection Address :****Block 1001 Bukit Merah Lane 3****#01-55 / #01 - 85 Singapore 159718****PARTICULARS OF VEHICLE**

| | | | | |
|---------------------|-----------------------|---------------------|--------|------|
| Registration No. : | SLW2098S | Mileage : | 107231 | Km/h |
| Make/Model : | TOYOTA CAMRY 2.0 AUTO | Radio/Casette : | Fitted | |
| Yr of Manuf/Regn : | 02 Oct 2015 | CD Disc Player : | Fitted | |
| Carrying Capacity : | 4seater | Air Conditioner : | Fitted | |
| Chassis No. : | MR053DK5100102822 | Clock : | Fitted | |
| Engine No. : | 6ARP043704 | Seat GBelt : | Fitted | |
| Colour : | Metallic Black | Wing Mirror : | Fitted | |
| Class : | Passenger(Private) | Other Accessories : | Fitted | |

PRE-ACCIDENT CONDITION (Static Check Only)

Body Work : Good
 Paint Work : Good
 Handbrake : Serviceable
 Footbrake : Serviceable
 Steering : Serviceable
 Any Apparent :
 Eng Modifications : None

VEHICLE VALUE

Market Value : -
 Wreck Value (Parf) : -

TYRE SIZE & CONDITION

| | | | | | |
|------------------|-----------|------|------------------|----------------|------|
| Front N/s Size : | 215/60R16 | 80 % | Front O/s Size : | 215/60R16 | 80 % |
| Make : | MICHELIN | | Make : | MICHELIN | |
| Rear N/s size : | 215/60R16 | 80 % | Rear O/s Size : | 215/60R16 | 80 % |
| Make : | MICHELIN | | Make : | MICHELIN | |
| Spare Size : | 215/60R16 | 80 % | Spare Size : | | |
| Make : | MICHELIN | | Make : | | |
| | | | Jack & Tools : | Intact/Missing | |

Type of Wheel Rims: Alloy**Note: The above percentage % represent the estimated remaining tyre threads.**

PRECISION APPRAISAL SERVICES

Insurance Loss Assessors / Adjusters Cargo Surveyors & Licensed Appraisers



VEHICLE REGISTRATION NO. : SLW 2098 S

APPENDIX A

POINT OF IMPACT

(Diagram A)

FRONT

(Diagram B)

FRONT

(Diagram C)


FRONT

(Diagram D)

FRONT

Direction of impact/damage marked (→)(X)


The vehicle sustained impact on its N/s Front Portion (see Diagram D)



REAR

OFF SIDE


NEAR SIDE



REAR

OFFSIDE


NEAR SIDE



REAR

OFF SIDE

NEAR SIDE



REAR

OFF SIDE

GENERAL DESCRIPTION OF DAMAGES

Parts damaged were: The front bumper and lower grille were dented.

ADJUSTMENTS & RECOMMENDATIONS

A static inspection was carried out on 01/06/2023 & our report is here with enclosed for your perusal. The Repairs Estimate submitted by M/s HONG SAN HONG WEI PTE LTD as per attached Appraisal Schedule have been revised and scrutinised thoroughly by us & in our opinion, we consider it to be fair and reasonable. The repairer has agreed to effect repairs to the owners satisfaction & to roadworthy condition on an agreed Part-By-Part Repair Basis of \$5,487.87 after deducting the Policy Excess Clause of \$ NA. As instructed, we have not authorised any of the repairs on your behalf.

| | Repairer's | | Our | |
|---------------------|------------|--------|---------|--------|
| | Estimate | Amount | Revised | Amount |
| Spares Parts | 6782 | 80 | 4497 | 87 |
| Towing Charges | X | X | X | X |
| PB Labour Charges | 800 | 00 | 600 | 00 |
| Others Misc Charges | 150 | 00 | 90 | 00 |
| Paintwork | 400 | 00 | 300 | 00 |
| Total | \$ 8132 | 80 | \$ 5487 | 87 |

Under normal circumstances, the duration of repairs should not exceed Nine(09) days excluding Pre-Repair Inspection (PRI) / Pre - Repair Survey (PRS) waiting time frame.

Attached photographs taken during inspection Forty-Eight(48) Photographs.

SPECIAL REMARKS

1. The inspection was conducted on a 'without prejudice' basis
2. On 06/05/2023, we examined the extent of damages.
3. On 07/06/2023, we examined the new replacement parts
4. On 09/06/2023, we examined the repaired vehicle

Yours Faithfully,

Ce



TF PHILIP FOO
AIMI CAE, AMIMI
AIAME, AMSAE-A
Licensed Appraiser/Adjuster

Inspection Report Date: 12 June 2023

VEHICLE REGN NO : SLW 2098 S
 OUR REFERENCE : PAS/HSHW/230152/TP
 INSPECTION REPORT DATE : 12-Jun-23

APPRAISEMENT SCHEDULE

CONTINUATION SHEET NO : 1

| S/No | Qty | Parts / Labour Descriptions | Remarks / Condition | Repairer's Estimate Amount \$ cts | Recommendation / Revised Amount \$ cts | |
|-----------------------------------|------|---|---------------------|--------------------------------------|---|----------------|
| <u>PARTS SUPPLY - LIST ITEMS</u> | | | | | | |
| 1 | 1pc | Front bumper | Badly Dented | 669.90 | Repair | |
| 2 | 1pc | Front bumper lower grille | Cracked 510.42 | 875.60 | 733.20 | |
| 3 | 1pc | Front bumper sensor N/s | Jammed 200 S/N | 387.00 | 387.00 | |
| 4 | 1pc | N/s Headlamp | Broken 2397.93 | 4770.30 | 4770.30 | |
| | | | | 6702.80 | 5890.50 | |
| Less: 25% discount | | | | 2908.35 25% 2181.26 | - | |
| | | | | 6702.80 | <u>4417.87</u> | |
| <u>SPECIAL NETT ITEMS</u> | | | | | | |
| 1 | 1set | Front no. plate w garnish | Dented/Bent/Defaced | 80.00 | 80.00 | |
| | | | | 6782.80 | <u>4497.87</u> | |
| <u>LABOUR & MISC. CHARGES</u> | | | | | | |
| 1 | | Remove the necessary affected parts, straighten n/s headlamp panel, repair front bumper and replace parts | | 800.00 | 600.00 300 | |
| 2 | | Putty and spraypaint on all affected parts | | 400.00 | 300.00 250 | |
| 3 | | Remove and refit front bumper sensors | | 100.00 | 60.00 40 | |
| 4 | | Rewire front portion and refocus n/s headlamp beam | 620 | 50.00 | 30.00 | |
| | | | | SUB / GRAND TOTAL | 8132.80 | 5487.87 |

2181.26
620.00
2001.00
3001.26
P/P

4 days

PRECISION APPRAISAL SERVICES

