

ASS. REC. BY:

REF:

Smo/ 2300 7393/Kny3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SCV 813U

Yr Regn:

021 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Esting

C.C.

2362

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

20957

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ACR 50 7166123

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

5

mm

Rear

R/Bal.

6

mm

L/Bal.

5

mm

L/Bal.

6

mm

D.O.A.

17/7/23

D.O.I.

21/7/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31/7 21:00 @ 2250h Calm (Red. \$3662.50, 61%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Enquire Vehicle Registration Details

Vehicle Registration Details

Vehicle No.
SCV813U

Make/ Model
TOYOTA/ESTIMA AERAS 2.4 CVT

Vehicle Scheme
-

Current Propellant
Petrol

Chassis No.
ACR507166123

Vehicle Type
Private Hire (Self-Drive) Station Wagon/Jeep/Land Rover

Owner's Details

Owner Name:
C & P RENT-A-CAR (PTE.) LTD.

Owner ID Type:
Company

NRIC/Passport/Company Cert No.:
197900477H

Registered Address:
41 PANDAN ROAD SINGAPORE 609283

Mailing Address:
-

Birth Date:

Registration Details

Previous Vehicle No
-

Effective Date of Ownership:
27 Feb 2020

Original Registration Date:
27 Feb 2020

Registration Date:
27 Feb 2020

No. of Transfers:
0

IU Label No.:
1129875572

Vehicle Specifications

Engine No :
2AZL024235

Chassis No.:
ACR507166123

Year of Manufacture:
2018

Primary Colour:
Black


Secondary Colour:
-

Passenger Capacity:
7

Engine Capacity / Power Rating :
2362 cc / -

Maximum Power Output:
125.0 kW (167 bhp)

Max Unladen Weight:



MODEL: TOYOTA ESTIMA

CHASSIS NO: ACR507100120			REPAIRER'S ESTIMATE(\$\$)
DESCRIPTION			
PARTS (LIST ITEMS)			
REAR BUMPER		\$ <i>R</i>	850.00
REAR BUMPER SIDE RETAINER RHS		\$ <i>CN</i>	150.00
REAR FENDER RHS <i>1211-70</i>		<i>R</i> \$	1,400.00
TAIL LAMP RHS		\$ <i>L</i>	950.00
		25%	\$ 3,350.00
			\$ 837.50
			\$ 2,512.50
SPECIAL NETT ITEMS			
	Total	\$	-
	TOTAL PARTS	\$	2,512.50

LKK Auto Consultants hence notify
the Repairer of the following:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00	60d
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00	50d
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	20d
4	To provide anti-rust treatment on affected areas	\$ 100.00	3d
	Labour Total :	\$ 3,400.00	
	TOTAL (PARTS & LABOUR):	\$ 5,912.50	