

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01 (Claims & Performance
Management)
Singapore 068897From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Steve Lim

Date: 31 Jul 2023

Preliminary Advice

Insured Vehicle No	: SNK5278J	Accident Date	: 18/07/2023
TP Vehicle No	: SFC936M	Assignment Date	: 21/07/2023
Make	: HONDA CROSSROAD	Est. Duration of Repair	: 3
Date of Inspection	: 24/07/2023		
Inspection At	: READY AUTOCARE (HQ) BLK 10 #03-06 AMK AUTO POINT, ANG MO KIO INDUSTRIAL PARK 2 A, ANG MO KIO AVE 5 SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,829.00
Revised Amount	:S\$	1,778.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,778.40
Lump Sum Repair	:S\$	1,400.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.