

ASS. REC. BY:

REF:

AIS / 230073941Kg

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Ready

of 569F

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 861K

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 11/27 Person Contacted: _____ Vehicle: IN / OUT

Veh No: SFC 936M Yr Regn: 11, 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A) : Wagon

Make: Honda Crossroad c.c. 1799

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 263290 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RT1 1005058

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / 8/Rim / STD A/Rim or

Tyre Size: F: 225/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Petlas

Front R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 18/7/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or cls frt

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>27/7</u>	<u>21 Rpt @ 1400. Car was used @ 1429, 90%</u>

Date/Time, File Pass to? : Prell. Report : Final Report

Date/Time, File Return to? _____

Days Of Repair: 3

Resurvey No. of Trip: _____

- Add Fee: : Site Insp (\$)
- : Interview (\$)
- : Tech Invs (\$)
- : Weekend (\$)

Survey Fee:	
Transportation:	
S - RS:	
Fees:	
Others:	
TOTAL:	

Report Format: NER-TP

Lump Sum / I.B.F. (\$) 1400

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047

Tel : 64810304 Fax : 64815587

Reg No : 200600989K

GST No : 200600989K

Allianz Insurance Singapore

Motorcar Claim Department

Estimate Repair

Date : 09/02/2011

Accident Involving SFC936M & SNK5278J On 18/7/2023 Along AMK AVE 3

Item	Descriptions	Amount
1	Front Right Door <i>182/warp</i>	\$ 1,250.00 ✓
2	Front Right Door Protector	\$ <i>223</i> 223.00 ✓
3	Front Right Side Skirt	\$ <i>376</i> 376.00 X
<i>208</i>		
Total For Parts		\$ 1,849.00

Labour & Misc

1	To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel Panel, Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure	\$ 500.00 <i>300</i>
2	Spray Painting For New And Repair Parts Including Supply Of Paints Materials	\$ 350.00 <i>220</i>
3	To Check Wiring For Proper Function	\$ 30.00 <i>20</i>
4	To Transfer Front Right Components From Old To New	\$ 100.00 <i>60</i>
Total For Labour		\$ 980.00

Ready Auto Care Pte Ltd
Sulynn - 96606551

Total For Parts & Labour \$ 2,829.00

No Of Days For Repair *4 Days*
3 days



*Not withheld
L/Perm & 1400h
Runway After Perm*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: