



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP23007395/Kqy3e2 Date: 01/08/2023 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBD 1069B	Veh. Inspected	SLN 7765P
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS23/2271	Excess (\$)	0.00
	Assign From	ANDY SEAH	Assign Date	21/07/2023
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA AXIO (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	NRE1610019492	Colour	METALLIC BROWN
	Odometer	398774 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	GREENTRAC	8 mm
	L/H Front Tyre	185/60 R15	GREENTRAC	8 mm
	R/H Rear Tyre	185/60 R15	GREENTRAC	8 mm
	L/H Rear Tyre	185/60 R15	GREENTRAC	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/07/2023	Inspection Date	21/07/2023
	Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		
5a. Remarks				
	A)REGISTRATION DATE: 17 MAY 2017 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	