SL0M237I0009 / Lai Luat (Meng Kee) Motor Pte Ltd ENTRY DATE ... TIME: 18/07/2023 17:29 (SGT) SUBMITTED BY: LHMK -3 VERSION: 1 (18/07/2023 17:29 (SGT))

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The Issue reporting may be referred to the Police for investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

18/07/2023 17:29 (SGT) Date of Submission **Actual Driver** Reported by 17/07/2023 14:00 (SGT) Date of Accident Exact Location of Accident Circuit Rd, Singapore Additional Location Information Country/State of Loss

Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SLN7765P

#### INSURED/POLICYHOLDER

Is company? KINETIC HOLDINGS PTE LTD Name Of Registered Owner 201618392N Company Reg No support@kinetic-alliance.com Email Address (Phone) +65-97522779 Mobile Phone No Alternative Phone No

### VEHICLE PARTICULARS

Toyota Axio Exact purpose for which vehicle was being used at time of Private hire accident

Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Private hire Vehicle Category ..... Transmission ..... Auto

INSURANCE COMPANY

China Taiping Insurance (Singapore) Pte. Ltd. Name of Insurance Company DMHCSNA00012202303 Policy Number / Cover Note Number

1500

#### DRIVER

CHAN HAN MENG Name of Driver S7563199E 28/08/1975 Date Of Birth Occupation Outdoor

Date Of Driving Pass 20/03/2007 Driving experience ..... 16 YEARS AND 4 MONTHS Gender Mobile Number (Phone) +65-90667483 Alt. Phone Number Email Address support@kinetic-alliance.com Address BLK 33 MARINE CRESCENT #16-103 Address complement ..... Postcode 440033 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Authorised driver Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions ..... Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 2 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email ..... Original language used in the statement PASSENGER 1 Name **UNKNOWN** Male DETAILS OF POLICE ACTION Was the accident reported to the police? Yes Police Station Name Bukit Merah West Neighbourhood Police Centre Police Station Phone No (Phone) +65-18003779999 Alt. Police Station Phone No (Fax) +65-63773923 Police Station Address 500 Bukit Merah View #01-01 Singapore 159682 Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT Please refer to the police report. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Reasons for not uploading a video of the accident The video is with the workshop, Thiam Heng Huat Pte Ltd.

DETAILS OF OTHER VEHICLE PROPERTY 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Prease report <u>correctly</u> the details of the accident to speed up the claims process.
- 7 This Form must be completed by the Policyholder and/or the Actual Drivet
- 3 Information provided must be as <u>truthful</u> and accurate as possible. Any wiful misripresentation or withholding of material facts may allow. insurance companies to repudiate policy liability
- The issue and acceptance of this Form by insurance companies is not an admission of policy habitly on the part of the insurance companies
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- // By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
- 8 Consent under the Personal Data Protection Act (POPA)

(a) My insurer, my workshop and the General Insurance Association of Singapore; GIA; may are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information ) and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insufed vehicle(s) involved in this accident shall be collectively referred to as the "Insurers": the Insurers lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims

(4) investigating the accident and/or my claims

(m) carrying out and/or dealing with my instructions or responding to any enquines by me

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers lawyers/law firms, may/are permitted to collect use disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may can be disclosed by any of the insurers and or GIA to their third party service providers or agents THE CANYERS (aw firms), which may be siled outside of Singapore, for one or more of the above Purposes


ins Signature ! Date & Time

We 18-07-23

Devera Signature of devel is not the proxyhold

INAME AS IN NEICHO CARS BOH JIT HOON

Sketch Plan



Velucle A: SLN7765P

Vehicle B: GBD 1069B

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	392N
Vehicle No.:	SLN7765P
Vehicle to be Exported:	No
ntended Deregistration Date:	19 Jul 2023
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA AXIO 1.5X A
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	2NR8644625
Chassis No.:	NRE1610019492
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,823.00
Original Registration Date:	17 May 2017
First Registration Date:	17 May 2017
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$6,823.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 May 2027
PARF Rebate Amount: Intended COE Rebate Details	\$4,434.00
COE Expiry Date:	16 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,106.00
COE Rebate Amount:	\$19,540.00
Total Rebate Amount:	\$23,974.00

The information contained herein is correct as at 19 Jul 2023

# Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721 Mobile: 82636295 Email: thiamhenghuat@gmail.com

Make/Model: TOYOTA AXIO

Engine/Chassis No.: NRE1610019492

Date of accident: 17.07.23 Damaged area: N/S Rear

Not Norman Date: 21/07/2023

1/Smp & 3/Ook Claim Type: TO

VRN: SLN77650

Me way After Paint Gdays

Date: 21/07/2023 Claim Type: TP VRN: SLN7765P

S/N	tems Parts description		(	QTY	U	NIT PRICE		AMOUNT		
1	Bootlid 909.50	13	270-10	1	\$	1,213.00	\$	1,213.00		
2	Bootlid inner trim	Su		1	\$	221.00	\$	221.00	X	
3	Bootlid hinge	R		2	\$	67.00	\$	134.00	X	
4	Bootlid lock	no	1	1	\$	259.00	\$	259.00	~	
5	Bootlid lock striker	1	1	1	\$	65.00	\$	65.00	X	
6	Bootlid key cylinder	/z	~	1	\$	194.00	\$	194.00	X	
7	Bootlid release cable	Se	_	1	\$	53.00	\$	53.00	X.	996
8	Bootlid weatherstrip	a	7	1	\$	185.00	\$	185.00	5011n	76.30
9	Licence plate lamp	r	n	2	\$	132.00	\$	264.00	X	
10	Bootlid chrome garnish	ne	1	1	\$	177.00	\$	177.00	-	
11	Bootlid hinge garnish	1	5	2	\$	49.00	\$	98.00	x	
12	Bootlid "TOYOTA" logo	Ne		1	\$	61.00	\$	61.00	_	
13	Bootlid "COROLLA" emblem	14	2	1	\$	47.00	\$	47.00	-	
14	Bootlid "AXIO" emblem	12	-	1	\$	42.00	\$	42.00		
15	End panel		n	1	\$	532.00	\$	532.00	X	
	End panel top garnish	/	201	1	\$	224.00	\$	224.00	V	
17	Rear bumper 565.70	Be	~	1	\$	788.00	\$	788.00		
18	Rear bumper side retainer	MI DI		2	\$	67.00	\$	134.00	4	
19	Rear bumper inner support bracket		-	2	\$	176.00	\$	352.00	X	
20	Rear bumper sponge	ns	P	1	\$	288.00	\$	288.00	X	
21	Taillamp n/s	B	70	1	\$	489.00	\$	489.00		
22	Taillamp sponge seal n/s	1	E	1	\$	8.00	\$	8.00	_	
23	Taillamp lower panel n/s	F	₹	1	\$	247.00	\$	247.00	*	
	Taillamp lower bracket n/s	CM	_	1	\$	33.00	\$	33.00		
25	Rear fender n/s	/	2	1	\$	898.00	\$	898.00	X	
	Rear fender inner trim n/s	/	5	1	\$	255.00	\$	255.00	X	
27	Rear fender cowling n/s	V	n	1	\$	174.00	\$	174.00	X	
28	Rear fender air duct n/s		5	1	\$	87.00	\$	87.00	X	
29	Rear windscreen glass moulding	1	~	1	\$	177.00	\$	177.00	×	
30	Rear bumper splash guard n/s		2		\$	87.00	\$	87.00	1	
31	Rear bumper reflector n/s 85.10	my cat &	×	1	\$	166.00	\$	166.00	X	
32	Rear bumper top bracket		In		\$	62.00	\$	124.00	X	
							\$	8,076.00		
					List	discount		25.00%		
						Total	Ś	6,057.00	1	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
  To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

No.	No. Parts description		QTY		UNIT PRICE			AMOUNT
1	Rear licence plate & frame	St	1	1	\$	55.00	\$	55.00
2	Reverse camera	1	2	1	\$	450.00	\$	450.00
3	Reverse sensor	she	2	1	\$	280.00	\$	280.00
4	Bootlid inner trim clips	N,	1	10	\$	5.50	\$	55.00
5	Rear bumper clips	M		12	\$	5.50	\$	66.00
6	Taillamp clips	N	~	6	\$	5.50	\$	33.00
7	Bootlid lamp clips	N	~	6	\$	5.50	\$	33.00
8	End panel sealant	N	~	1	\$	100.00	\$	100.00
9	End panel top garnish clips	n	~	6	\$	5.50	\$	33.00
10	Rear fender cowling clips n/s	N	~	6	\$	5.50	\$	33.00
11	Rear windscreen glass sealant	^	~	1	\$	100.00	\$	100.00
12	Rear fender inner trim clips n/s	1	m	8	\$	5.50	\$	44.00
13	Sundries	N	n	1	\$	50.00	\$	50.00
						Total	Ś	1,332.00

Labo	our		
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$ 1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	5	\$ 1,000.00
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$ <i>№</i> 150.00
6	To rust proof all affected portions after repair.	0.5	\$ 100.00
	То	\$ 2,800.00	