

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Foo Ai Ngho

Date: 21 Jul 2023

**Preliminary Advice**

Vehicle No	: YQ1096G	Accident Date	: 17/07/2023
Make	: ISUZU NPR85UH5A	Policy No.	: DMCG23007316
Assignment Date	: 20/07/2023	Excess	: S\$500.00
Date of Inspection	: 21/07/2023	Est. Duration of Repair	: 7
Inspection At	: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ) 1 DEFU LANE 6 SINGAPORE 539365		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,027.40
Revised Amount	:S\$	10,701.30
Check Items (Estimated)	:S\$	4,009.50
Total	:S\$	14,710.80
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	16,234.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,766.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Lump Sum Repair

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .