

(08/11/13) wef

ASS. REC. BY: Marcus

REF: CS/EG/23007406/Ug43

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YQ1096G
at Workshop m/s AIM

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: \$85k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 214816234

Date/Time _____ Action / Instruction Rep 14h

1/8/23 2/5 \$10,900 inform all Ten cash \$16177.40, 60%

Veh No: YQ1096G Yr Regn: 25/06/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CM

Make: Suzuki NPR85 c.c 2999

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 105182 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JAANPR85HK 7100220

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 HPSR 16
R: Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or linglong

Front

Rear

R/Bal. 7 mm R/Bal. 7/7 mm

L/Bal. 7 mm L/Bal. 7/7 mm

D.O.A. 17/07/23 D.O.I. 21/7/23

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 7

1)

☐ : Final Report

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:

Transportation:

2)

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format : MER-OD

Lump Sum / I.B.I. (\$) 10900

Automobile Integrated Management Pte Ltd (Co.Reg.No:201605297G)

1 Defu Lane 6
Singapore 539365
Tel: 91198371 Email: automim.claim@gmail.com

Marcus 21/7/23

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	AC2023030/OD
Policy No:	DMCG23007316	Date of Loss:	17/07/2023
Vehicle Reg. No.:	YQ1096G	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	IMPETUS CONCEPTUS PTE LTD		
Make/Model:	ISUZU NPR85UH5A, 3.0 D (M)	Vehicle Reg. Date:	25/06/2019
Vehicle Colour:	White		
Engine No:	4JJ14B7018	Chassis No:	JAANPR85HK7100220
Odometer:	105182 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	20,167.40
Miscellaneous Items	0.00
Labour	6,860.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	27,027.40
+ GST 8.00% (S\$)	2,162.19
Nett Amount (S\$)	29,189.59

This claim is handled by: OPSTEAM1

Generated using Merimen e-Claims Internet Estimation & Adjusting System

not Authorized
21/7/23
2/5 \$10,900
Excess \$500
To be paid after repair
7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Jul 2023)
Parts: N/A ISUZU NPR85UH5A 3.0 D (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Automobile Integrated Management Pte Ltd/YQ1096G/20/07/2023 11:18
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT WINDSCREEN - GLASS <i>3rd</i>	0.00	0.00	*1,344.00 F	✓
2	1		*FRONT WINDSCREEN MOULDING <i>1st</i>	0.00	0.00	*205.00 F	✓
3	1		*FRONT WIPER ARM L/R X2PCS <i>1st</i>	0.00	0.00	*120.00 F	✓
4	1		*FRONT WIPER BLADE L/R X2PCS <i>1st</i>	0.00	0.00	*76.00 F	✓
5	2		*FRONT WIPER NOZZLE <i>1st</i>	0.00	0.00	*44.00 F	X
6	1		*FRONT PANEL ISUZU LETTERING <i>1st</i>	0.00	0.00	*100.00 F	X
7	1		*FRONT PANEL REWARD NN STICKER <i>1st 11</i>	0.00	0.00	*22.00 F	X
8	1		*FRONT PANEL RUBBER <i>1st</i>	0.00	0.00	*30.00 F	X
9	1		*FRONT WIPER LINKAGE <i>1st</i>	0.00	0.00	*155.00 F	X
10	1		*Wiper motor, front <i>1st</i>	0.00	0.00	*322.00 F	X
11	1		*FRONT CENTRE GRILLE <i>1st</i>	0.00	0.00	*389.00 F	X
12	1		*Wiper panel <i>1st</i>	0.00	0.00	*386.00 F	X
13	1		*Wiper tank, front <i>1st</i>	0.00	0.00	*120.00 F	X
14	1		*Bumper, front <i>1st</i>	0.00	0.00	*480.00 F	X
15	1		*FRONT BUMPER BRACKET L/R X2PCS <i>1st</i>	0.00	0.00	*196.00 F	X
16	1		*FRONT CORNER PILLAR BRACKET <i>1st</i>	0.00	0.00	*1,050.00 F	X
17	1		*LH FRONT DOOR ASSY <i>1st</i>	0.00	0.00	*880.00 F	X
18	1		*LH/FRONT DOOR WEATHERSTRIP <i>1st</i>	0.00	0.00	*128.00 F	X
19	1		*LH/FRONT DOOR OUTER MOULDING <i>1st</i>	0.00	0.00	*50.00 F	X
20	1		*LH/FRONT DOOR OUTER PROTECTOR <i>1st</i>	0.00	0.00	*48.00 F	X
21	2		*LH/FRONT DOOR HINGE <i>1st</i>	0.00	0.00	*150.00 F	X
22	1		*LH/FRONT DOOR LOWER GARNISH <i>1st</i>	0.00	0.00	*125.00 F	X
23	1		*LH/FRONT DOOR RUBBER <i>1st</i>	0.00	0.00	*165.00 F	X
24	1		*LH/Front Door handle inner <i>1st</i>	0.00	0.00	*54.00 F	X
25	1		*LH/Front Door trimboard <i>1st</i>	0.00	0.00	*329.00 F	X
26	1		*LH/Front Door Glass <i>1st</i>	0.00	0.00	*295.00 F	X
27	1		*LH/Front Door Body Rubber <i>1st</i>	0.00	0.00	*188.00 F	X
28	1		*LH/Front Door Rubber Guide <i>1st</i>	0.00	0.00	*188.00 F	X
29	1		*LH FRONT DOOR WHEEL ARCH GARNISH <i>1st</i>	0.00	0.00	*140.00 F	X
30	1		*FRONT PILLAR LOWER TRIM <i>1st</i>	0.00	0.00	*158.00 F	X
31	1		*FRONT LOWER SIDE CONDENSER <i>1st</i>	0.00	0.00	*600.00 F	X
32	1		*FRONT CONDENSER FAN COWLING <i>1st</i>	0.00	0.00	*231.00 F	X
33	1		*FRONT CONDENSER FAN MOTOR <i>1st</i>	0.00	0.00	*400.00 F	X
34	1		*Radiator <i>1st</i>	0.00	0.00	*1,943.00 F	X
35	1		*AIRCON SUCTION PIPE <i>1st</i>	0.00	0.00	*180.00 F	X
36	1		*AIRCON DISCHARGE PIPE <i>1st</i>	0.00	0.00	*220.00 F	X
37	1		*AIRCON BLOWER <i>1st</i>	0.00	0.00	*720.00 F	X
38	1		*AIRCON COOLING COIL <i>1st</i>	0.00	0.00	*980.00 F	X
39	1		*FRONT DASHBOARD <i>1st</i>	0.00	0.00	*1,277.00 F	X
40	1		*FRONT DASHBOARD REINFORCEMENT <i>1st</i>	0.00	0.00	*735.00 F	X
41	1		*LH DASHBOARD COVER <i>1st</i>	0.00	0.00	*295.00 F	X
42	1		*LH FRONT CONSOLE COVER <i>1st</i>	0.00	0.00	*315.00 F	X
43	1		*Door lock LH, front <i>1st</i>	0.00	0.00	*153.00 F	X
44	1		*Panel, front <i>1st</i>	0.00	0.00	*540.00 F	X
45	2		*Panel outer, front <i>1st</i>	0.00	0.00	*350.00 F	X
46	1		*Headlamp LH <i>1st</i>	0.00	0.00	*245.00 F	X
47	2		*Front wing mirror <i>1st</i>	0.00	0.00	*90.00 F	X

48	2	*Front wing arm	17	0.00	0.00	*430.00 F	X
49	1	*Front wing mirror o LH	17	0.00	0.00	*38.00 F	X
50	1	*Front pillar LH <i>inner</i>	<i>Body</i>	0.00	0.00	*450.00 F	
51	1	*Door Lock striker LH, front	17	0.00	0.00	*205.00 F	X

F=Franchise part.

Sub Total (S\$)	18,334.00
+ Margin on L,N Items 10.00% (S\$)	1,833.40

Total Parts (S\$)	20,167.40
-------------------	-----------

Automobile Integrated Management Pte Ltd/YQ1096G/20/07/2023 11:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	W/screen, front	New	200.00 100
2	Remove aircon blower and cooling coil, top up aircon gas	New	250.00 100
3	To remove and refit radiator assy and refill coolant	New	80.00 X
4	To check electrical wiring	New	80.00 20
5	To remove and refit front dashboard	New	350.00 250
6	To respray painting	New	1,600.00 800
7	To remove and refit cabin	New	800.00 X
8	Panel beating, cut, weld, remove & replacing above parts	New	3,500.00 1200
Gross Labour Cost (\$\$)			6,860.00

Automobile Integrated Management Pte Ltd/YQ1096G/20/07/2023 11:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >