



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile		CS3/GRB23005572/Tqy3-1	
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Ref: CS/III23005572/Tqy3	Date: 01/06/2023 21/07/2023
		Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLP 4338Z	Veh. Inspected	SJP 5385D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	LOGAN	Assign Date	01/06/2023 21/07/2023
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	29/05/2023	Inspection Date	01/06/2023
Survey held at	HORIZON AUTO TUNERS 25 KAKI BUKIT ROAD 4 #01-48 SYNERGY @ KB SINGAPORE (417800)		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			