

FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DPHUA CHYE KIAT
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Estimate : ES012691


Attention : Motor Claim Department
Contact : 9875 8005Date : 24/07/2023
Vehicle Num. : SLD 5374A
Make/Model : MAZDA 6 SP.6EAT-2016
Chassis/Eng# : JM6GJ1072G0240594
Accident Date : 20/07/2023
Claim No. :
Reference : TP - GEG AGT AIG ASIA PACIFIC
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1 PC	HEADLAMP		3,259.00
2.	1 PC	RH HEADLAMP LOWER BRACKET		78.00
3.	1 PC	RH HEADLAMP PANEL		610.00
4.	1 PC	RH RADIATOR CHROME MOULDING		198.00
5.	1 PC	RH RADIATOR CHROME MOULDING BASE		88.00
6.	1 PC	RH FRONT FENDER		485.00
7.	1 PC	FRONT BUMPER		1,358.00
8.	1 PC	RH FRONT BUMPER SIDE RETAINER		55.00
9.	1 PC	RH FOG LAMP CHROME		165.00
10.	1 PC	WIPER WASHER TANK		148.00
11.	1 PC	RH HEADLAMP MODULE		1,550.00
List Total S\$:				7,994.00
20.00% Discount S\$:				1,598.80
				6,395.20
SPECIAL NETT ITEMS :				
1.	1 SET	FRONT BUMPER CLIP		60.00
2.	1 SET	FRONT BUMPER RIVETS		60.00
Special Nett Total S\$:				120.00

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S[575721] Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
 Branches : Tampines St 93 Blk 9006 #01-200 S[528840] Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S[128226] Tel: 6779-5665 Fax: 6779-1110
 Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D

PHUA CHYE KIAT
C/O 176 SIN MING DRIVE #01-06/07
SIN MING AUTOCARE 575721

Attention : Motor Claim Department
Contact : 9875 8005

Estimate : ES012691

Date : 24/07/2023
Vehicle Num. : SLD 5374A
Make/Model : MAZDA 6 SP.6EAT-2016
Chassis/Eng# : JM6GJ1072G0240594
Accident Date : 20/07/2023
Claim No. :
Reference : TP - GEG AGT AIG ASIA PACIFIC
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :				
		TO CHECK WIRING & FOCUS HEADLAMP		50.00
		TO RESET/RECALIBRATE HEADLAMP MODULE, CODING		380.00
		TO REMOVE NECESSARY PARTS, TO REPAIR INNER PANEL,		
		REPLACE HEADLAMP PANEL, DAMAGE PARTS AND ALIGN THE SAME		800.00
		TO PUTTY AND SPRAY PAINT BONNET, FRONT BUMPER,		
		RH FRONT FENDER		800.00
Labour Total S\$:				2,030.00

E. & O.E.	Total S\$:	8,545.20
-----------	-------------	----------

=====

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg