

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0693/2023/EQ
DATE : 25-Jul-23
WIP : 30244

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 26/07/2023.

YOUR INSURED VEH NO : SCX 9950 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. STEVEN ANG CHIN HAN (STEVEN HONG ZHENHAN)
ADDRESS : 16 CANTONMENT ROAD
#14-81
SINGAPORE 085701
TELEPHONE : HP +65 91881666
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 7020100809
VEHICLE NO : **SMP 7430 H**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S-TRONIC
MODEL YEAR : 14/10/2019
ENGINE NO : DLH 062100
CHASSIS NO : WAUZZZF25LN005628
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Jul-23
PLACE OF ACCIDENT : TANJONG PAGAR ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 7430 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, AB PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS.	S/N \$	1,800.00	
2	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOOR'S MULTI-LOCK SYSTEMS AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES AND RENEW IF NECCESARY.	S/N \$	800.00	
3	TO DISMANTLE AND RENEW LHS FRONT DOOR, LHS REAR DOOR AND LHS SILL PANEL TRIM. TO CUT OUT AND WELD LHS B-PILLAR WITH LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	6,400.00	
4	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, DOOR HINGES, DOOR HANDLES, LHS SILL PANEL TRIM, LHS SILL PANEL, LHS B-PILLAR AND DOOR ENTRANCES.	\$	6,000.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		:	\$ 15,192.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 7430 H

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT DOOR - LH	1	\$ 4,750.00	
2	FRONT DOOR OUTER SEAL	1	\$ 223.00	
3	FRONT DOOR ATTACHMENT PARTS	1	\$ 386.00	
4	FRONT DOOR CATCH - LH	1	\$ 141.00	
5	FRONT WINDOW REGULATOR WITHOUT MOTOR - LH	1	\$ 408.00	
6	REAR DOOR	1	\$ 4,750.00	
7	REAR DOOR OUTER SEAL	1	\$ 223.00	
8	REAR DOOR SEAL BRACKET - LH	1	\$ 168.00	
9	REAR DOOR STONE CHIP PROTECTION FILM - LH	1	\$ 146.00	
10	REAR DOOR ATTACHMENT PARTS	1	\$ 386.00	
11	REAR DOOR OUTER SEAL - LH	1	\$ 219.00	
12	REAR DOOR HINGE - LH LOWER	1	\$ 181.00	
13	REAR DOOR CATCH - LH	1	\$ 141.00	
14	REAR SIDE MEMBER TRIM - LH	1	\$ 1,016.00	
15	ATTACHMENT PARTS	1	\$ 144.00	
16	ADHESIVE TAPES	1	\$ 68.00	
17	REAR PILLAR A/B WITH FRAME MEMBER - LH	1	\$ 3,820.00	
18	FRONT DOOR SILL TRIM STRIP - LH	1	\$ 221.00	
19	REAR DOOR SILL TRIM STRIP - LH	1	\$ 140.00	
20	AIRBAG / CHILD'S SEAT STICKER WITH PICTOGRAM	1	\$ 28.00	
SUB TOTAL SPARE PARTS		:	\$ 17,559.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 7430 H**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	CHILD SEAT NOTICE	1	\$ 24.00	
22	ACRYLIC SEALANT	S/N	\$ 180.00	
23	CAVITY WAX	S/N	\$ 140.00	
24	STONE CHIP	S/N	\$ 180.00	
25	METAL FILLER POWDER	S/N	\$ 280.00	
26	SUNDRIES		\$ 600.00	
TOTAL SPARE PARTS		:	\$ 18,963.00	
TOTAL LABOUR CHARGES		:	\$ 15,192.00	
GRAND TOTAL		:	\$ 34,155.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT