

RS Bikes Centre

No.1 Kaki Bukit Avenue 6 #02-45 AutoBay Singapore 417883

TEL : 67478202 FAX : 67476907

Date	: 22-Jun-2023	23-Mar-21
Model	: Honda ANF 125	
Vehicle No.	: FBB 4066 A	
Name	: Mohd Saifullah Bin Zainal Abidin	
Address	: C/o No. 1 Kaki Bukit Ave 6 #02-45 AutoBay@Kaki Bukit Singapore 417883	

Final bill for the above-mentioned as follows :

Lump sum repair costs : **\$ 2400.00**

Singapore Dollars : Two Thousand And Four Hundred Only

MC-COY

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Invoice No 21018-03/AY

Billing Name & Address

Date 22 Jun 2023

Mohd Saifullah Bin Zainal Abidin
C/o No. 1 Kaki Bukit Ave 6
#02-45 AutoBay@Kaki Bukit
Singapore 417883

Vehicle No : FBB 4066 A

Model : Honda ANF 125

Item	Descriptions	Amount S\$
1	Date of inspection : <u>23 Mar 2021</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Develop photographs - Storage of digital photographs - Submission of photographs <u>162</u> copies	
3	Transportation Charges	
4	Final Inspection Total	<u>\$ 562.00</u>
	SDLS : FIVE HUNDRED AND SIXTY-TWO ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Mc-Coy Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

Report Reference : TP / 21018-03/AY / 2021
Date of Report : 22 Jun 2023

Mohd Saifullah Bin Zainal Abidin
C/o No. 1 Kaki Bukit Ave 6
#02-45 AutoBay@Kaki Bukit
Singapore 417883

**THIRD PARTY SURVEY
ACCIDENT HAPPENED ON 29 Jan 2021**

Workshop Address : RS Bikes Centre
No.1 Kaki Bukit Avenue 6
#02-45 AutoBay@Kaki Bukit
Singapore 417883

As per your instruction dated **23 Mar 2021** with regard to the above matter. We have carried out a physical inspection on the said vehicle **FBB 4066 A**. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No	: FBB 4066 A	Engine No	: NF125MME5000439
Model	: Honda ANF 125	Mileage	: -
Year / Capacity	: 2007/125	Colour	: Blue
Chassis No	: NF125MM5000439		

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT O/S	: 70/90-17	King Lana	4.00	mm	Sport
REAR O/S	: 80/90-17	Dunlop	4.00	mm	Sport



No. 1 Kaki Bukit Ave 6 #01-28 AutoBay @ Kaki Bukit Singapore 417883
Tel: 6748 6653 Fax: 67471017 Registration No: 200723252D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the front n/s portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 8 working days to complete.
5. Enclosed number of photograph : 162 copies.
6. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.
7. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **FBB 4066 A**
 Report No: **TP/ 21018-03/AY / 2021**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Front fender	Damage	\$ 80.00	\$ 80.00
2	Fork inner tubes	Damage	\$ 220.00	\$ 220.00
2	Fork outer tubes	Damage	\$ 260.00	\$ 260.00
1	Fork under bracket	Damage	\$ 170.00	\$ 170.00
1	Front rim shaft	Damage	\$ 38.00	\$ 38.00
1	Front sport rim	Damage	\$ 195.00	\$ 195.00
1	Top fairing	Damage	\$ 78.00	\$ 78.00
1	Headlamp	Damage	\$ 58.00	\$ 58.00
1	Front signal	Damage	\$ 32.00	\$ 32.00
2	Front side fairings	Damage	\$ 240.00	\$ 240.00
1	Mirror	Damage	\$ 36.00	\$ 36.00
1	Handle bar	Damage	\$ 60.00	\$ 60.00
1	Handle bar end	Damage	\$ 15.00	\$ 15.00
1	Centre fairing	Damage	\$ 45.00	\$ 45.00
1	Front footrest	Damage	\$ 32.00	\$ 32.00
1	Gear pedal	Damage	\$ 25.00	\$ 25.00
1	Rear footrest	Damage	\$ 32.00	\$ 32.00
1	Rear footrest bracket	Damage	\$ 90.00	\$ 90.00
1	Tail board	Damage	\$ 95.00	\$ 95.00
			<u>\$ 1801.00</u>	<u>\$ 1801.00</u>
	Discount	10.0%	\$ 180.10	\$ 180.10
			<u>\$ 1620.90</u>	<u>\$ 1620.90</u>

<u>Special Nett Items</u>				
1	Front number plate	Necessary	\$ 10.00	\$ 10.00
1	Rear number plate	Damage	\$ 18.00	\$ 18.00
1	Steering cone (1 set)	Necessary	\$ 75.00	\$ 75.00
1	Rear box	Damage	\$ 180.00	\$ 180.00
1	Rear box bracket	Damage	\$ 100.00	\$ 100.00
1	E.R.P IU	Damage	\$ 160.00	\$ 160.00
1	Basket	Damage	\$ 60.00	\$ 60.00
			<u>\$ 603.00</u>	<u>\$ 603.00</u>

Spare Parts Total \$ 2223.90 \$ 2223.90

Vehicle No: **FBB 4066 A**
Report No: **TP/ 21018-03/AY / 2021**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 2223.90	\$ 2223.90
1	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 600.00	\$ 400.00
2	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 600.00	\$ 400.00
Total		<u>\$ 3423.90</u>	<u>\$ 3023.90</u>

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 2400.00

SDLS: TWO THOUSAND FOUR HUNDRED ONLY



Qualified Appraiser













































































































