

SMR.

TOTAL

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08

Sin Ming AutoCare Singapore 575721

Tel No. : 64556268 Fax No. : 64555166

E-Mail : info@ktauto.com.sg

Website : www.ktauto.com.sg

Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

FIRST CAPITAL INSURANCE LIMITED

30 ROBINSON ROAD #10-01/02 ROBINSON TOWERS
SINGAPORE 048546

Attention : Motor Claim Department

Contact : 6507 6848 Fax No. : 6507 3849

Estimate : ES000522

Date : 24/07/2023

Vehicle Num. : SLX 5837 B

Make/Model : BMW 116D-2018

Chassis/Eng# : WBA1V720X05G87647/39945238B37D

Accident Date : 24/07/2023

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|-------|--|--|--|
| 1. | 1 | LIST ITEMS : | | |
| 2. | 1 | REAR BOOTH LID <i>bt</i> | | |
| 3. | 1 | REAR BUMPER UNIT <i>de</i> | | |
| 4. | 2 | REAR BUMPER SIDE RETAINER <i>LH-? RH X</i> | | |
| 5. | 1 | REAR BUMPER REINFORCEMENT <i>?</i> | | |
| 6. | 2 | REAR NUMBER PLATE LIGHT BULB <i>?</i> | | |
| 7. | 1 | REVERSE CAMERA <i>?</i> | | |
| 8. | 1 | REAR EXHAUST MUFFLER BOX <i>Rx</i> | | |
| 9. | 2 PCS | REAR BUMPER REVERSE SENSOR <i>nm</i> | | |
| 9. | 1 SET | REAR BUMPER REVERSE SENSOR HARDNESS <i>X</i> | | |

List Total S\$:

- | | | | | |
|----|---|-------------------------------|--|--|
| 1. | 1 | NETT ITEMS : | | |
| 2. | 1 | REAR NUMBER PLATE WITH CASING | | |
| | | WINDSCREEN SEALANT | | |

45 58.00 *61*
38.00 *4*
96.00

Nett Total S\$:

LABOUR :

LABOUR FEES:

- TO KNOCK AND REPAIR DAMAGED PARTS
- TO REMOVE AND CHANGE ALL DAMAGED PARTS
- TO PUTTY APPLY PRIMER & SPRAY PAINT THE AFFECTED AREAS
- TO SPRAY PAINT ALL DAMAGED PARTS
- TO CHECK ALL ELECTRICAL WIRING
- TO CHECK ALL LIGHTING UNIT
- TO REMOVE AND REFIT REAR WINDSCREEN TO FACILATE REPAIR

600 1,400.00
600 850.00
50 280.00
120 240.00
2,770.00

Labour Total S\$:

E. & O.E.

Total S\$: 2,866.00

LKK Auto Consultants hence notify

the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

for KIAN TEONG AUTO CENTRE

Please do not hesitate to contact us at the above number if there is any other further enquire.
We thank you for your kind attention. Your prompt reply is greatly appreciated.

Tan Jiah 97495747/62563561
Up 24/7/23 2 Spm
4/5 hours after repair
Tan Jiah @ Khandu-h
5 days