

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: HL Assurance Pte Ltd
11 Keppel Road
#11-01 ABI Plaza
Singapore 089057From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Romeo Jonnalyn Alaan

Date: 26 Jul 2023

Preliminary Advice

Vehicle No	: SMR8598R	Accident Date	: 21/07/2023
Make	: SKODA OCTAVIA	Policy No.	: MP321360
Assignment Date	: 24/07/2023	Excess	: S\$0.00
Date of Inspection	: 25/7/2023	Est. Duration of Repair	: 8
Inspection At	: VOLKSWAGEN GROUP SINGAPORE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,615.95
Revised Amount	:S\$	16,621.40
Check Items (Estimated)	:S\$	2,451.84
Total	:S\$	19,073.24

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	103,000.00
COE / PARF Rebate	:S\$	39,185.00
Salvage Value	:S\$	
Margin for Repair	:S\$	63,815.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .