



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS3/AIS23007486/Rvp3 Date: 24/07/2023 Code: AIS	
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>				
	Insured Veh.	SJY 9032Z	Veh. Inspected	SNG 6994P
	Policy No.		Coverage (\$)	0.00
	Claim No.	2023 32010942JK	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	24/07/2023
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
	Accident Date	19/07/2023	Inspection Date	25/07/2023
	Survey held at	GOLD AUTOWORKS PTE LTD 48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586		
<b>5a. Remarks</b>				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			