

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Zheng Hanyang

Date: 26 Jul 2023

Preliminary Advice

Vehicle No	: SKS7754G	Accident Date	: 18/07/2023
Make	: TOYOTA COROLLA ALTIS	Policy No.	: DMPG23005184
Assignment Date	: 24/07/2023	Excess	: S\$500.00
Date of Inspection	: 25/07/2023	Est. Duration of Repair	: 0
Inspection At	: SPECIALISTS MOTOR PTE LTD (HQ) BLK 3018A UBI ROAD 1, #01-24/25/26 SINGAPORE 408711		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	
Total	:S\$	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	33,000.00
COE / PARF Rebate	:S\$	20,037.00
Salvage Value	:S\$	
Margin for Repair	:S\$	12,963.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :