

(08/11/13) Web

ASS. REC. BY: [Signature]

REF:

CS/CT123007505/R9p3

C
6794**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: 4P 2085Lat Workshop m/s SNH A4 PGEof PIONEER NORTH ADInsured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 550

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

<u>2</u>	
N/S	O/S

Bal. or Market Value: 39K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 4P 2085LYr Regn: 2016 / APRType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: SUZUKIc.c. 2999Colour: WHITE

A/C: Insured / Std / NI / NA

Sp. Reading: _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JANHR85EF7100439Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt or _____Brake: Inorder / Jammed / Leaked / Burnt or _____Modi: NH / S/Rim / STD A/Rim or _____

Tyre Size: F: _____

195R15R: 165R14

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 7 mmR/Bal. 5/5 mmL/Bal. 7 mmL/Bal. 5/5 mmD.O.A. 08/07/23D.O.I. 28/07/23

Survey held at

SNH A4 PGEDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

REPAIR LIMIT - 37K

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

) S + RS, SI

) Photos

) Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

TOTAL

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCVSNW00023062301	Date of Loss:	08/07/2023
Vehicle Reg. No.:	YP2085L	Driveable?	
Driver Age/Info:	37 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	PACIFIC BIOENERGY FATS AND TRADING PTE LTD	Contact No:	+6593387352
Driver:	HONG JINBAO		
Make/Model:	ISUZU NHR85AUE4A, 3.0 D R1 (M)	Vehicle Reg. Date:	11/04/2016
Vehicle Colour:	WHITE		
Engine No:	4JJ12F3756	Chassis No:	JAANHR85EF7100439
Odometer:	5 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	25		
Description of Accident/Loss	AS PER POLICE RE		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	65.00
Labour	0.00
Paintwork Labour	4,420.00
Towing	0.00
	0.00
Gross Total (S\$)	4,485.00
+ GST 8.00% (S\$)	358.80
Nett Amount (S\$)	4,843.80

This claim is handled by: JANICE CHANG SIEW YIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Jul 2023)	
Parts:	N/A	ISUZU NHR85AUE4A 3.0 D R1 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP2085L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE <i>bt</i>	0	0.00	*25.00 FS
2	1		*FRT BUMPER <i>form</i>	0.00	0.00	-
3	2		*FRT BUMPER BRACKET <i>2. RH-bt/LH-7.</i>	0.00	0.00	-
4	2		*FRT BUMPER FOGLAMP <i>?</i>	0.00	0.00	-
5	1		*FRT GRILLE <i>low</i>	0.00	0.00	-
6	10		*FRT GRILLE CLIPS <i>m</i>	0.00	0.00	-
7	2		*FRT HEADLAMP <i>low</i>	0.00	0.00	-
8	2		*FRT HEADLAMP BRACKET <i>H</i>	0.00	0.00	-
9	2		*FRT SIGNAL LAMP <i>low</i>	0.00	0.00	-
10	2		*FRT HEADLAMP LOWER SEAL <i>m</i>	0.00	0.00	-
11	1		*FRT PANEL <i>bt</i>	0.00	0.00	-
12	1		*FRT EMBLEM <i>m</i>	0.00	0.00	-
13	2		*FRT CORNER PANEL <i>com</i>	0.00	0.00	-
14	8		*FRT CORNER PANEL CLIPS <i>m</i>	0.00	0.00	-
15	1		*FRT CORNER PANEL COVER <i>com</i>	0.00	0.00	-
16	1		*FRT PANEL NH STICKER <i>m</i>	0.00	0.00	-
17	2		*FRT WIPER ARM <i>bt</i>	0.00	0.00	-
18	2		*FRT WIPER BLADE <i>m</i>	0.00	0.00	-
19	1		*FRT WIPER LINKAGE <i>?</i>	0.00	0.00	-
20	1		*FRT WIPER MOTOR <i>?</i>	0.00	0.00	-
21	1		*FRT WIPER ARM COVER(LH) <i>com</i>	0.00	0.00	-
22	2		*FRT WIPER ARM WASHER <i>m</i>	0.00	0.00	-
23	1		*FRT WINDSCREEN <i>low</i>	0.00	0.00	-
24	1		*FRT WINDSCREEN MOULDING <i>m</i>	0.00	0.00	-
25	1		*FRT WINDSCREEN SEALANT <i>m</i>	0	0.00	*40.00 FS
26	1		*FRT WINDSCREEN INNER MOULDING <i>m</i>	0.00	0.00	-
27	1		*ERP UNIT <i>com</i>	0	0.00	-
28	2		*FRT WINDSCREEN PILLAR <i>bt</i>	0.00	0.00	-
29	1		*FRT WINDSCREEN LOWER MOULDING <i>m</i>	0.00	0.00	-
30	2		*FRT WINDSCREEN SIDE COVER <i>at</i>	0.00	0.00	-
31	2		*FRT WINDSCREEN SIDE HOLDER <i>m</i>	0.00	0.00	-
32	2		*FRT WINDSCREEN INNER PILLAR <i>bt</i>	0.00	0.00	-
33	2		*FRT WIPER NOZZLE <i>dis</i>	0.00	0.00	-
34	2		*FRT WIPER NOZZLE WASHER <i>dis</i>	0.00	0.00	-
35	1		*FRT SIDE MIRROR(LH) <i>low</i>	0.00	0.00	-
36	1		*FRT SIDE MIRROR ARM(LH) <i>bt</i>	0.00	0.00	-
37	1		*FRT SIDE MIRROR ARM CAP(LH) <i>m</i>	0.00	0.00	-
38	1		*FRT SIDE MIRROR (ROUND)(LH) <i>m</i>	0.00	0.00	-
39	1		*FRT SIDE MIRROR (RH) <i>m</i>	0.00	0.00	-
40	1		*FRT SIDE MIRROR ARM(RH) <i>bt</i>	0.00	0.00	-
41	1		*FRT SIDE MIRROR ARM CAP(RH) <i>m</i>	0.00	0.00	-
42	1		*FRT ROOF PANEL <i>low</i>	0.00	0.00	-
43	1		*FRT ROOF UPHOLSTERY <i>dis</i>	0.00	0.00	-
44	1		*FRT ROOF UPHOLSTERY TRIM <i>dis</i>	0.00	0.00	-
45	8		*FRT ROOF UPHOLSTERY CLIPS <i>m</i>	0.00	0.00	-

o.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	1		*FRT ROOF SUNSHADE <i>de</i>			
47	1		*FRT CABIN LAMP <i>ca</i>	0.00	0.00	-
48	1		*FRT DOOR(LH) <i>bu</i>	0.00	0.00	-
49	1		*FRT DOOR LAMP(LH) <i>son</i>	0.00	0.00	-
50	2		*FRT DOOR HINGE(LH) <i>bt</i>	0.00	0.00	-
51	1		*FRT DOOR LOCK(LH) <i>bt</i>	0.00	0.00	-
52	1		*FRT DOOR LATCH(LH) <i>bt</i>	0.00	0.00	-
53	1		*FRT DOOR CHECKER(LH) <i>bt</i>	0.00	0.00	-
54	1		*FRT DOOR TRIM BOARD(LH) <i>de</i>	0.00	0.00	-
55	1		*FRT DOOR OUTER HANDLE(LH) <i>de</i>	0.00	0.00	-
56	1		*FRT DOOR LOWER SEAL(LH) <i>an</i>	0.00	0.00	-
57	1		*FRT DOOR RUBBER(LH) <i>an</i>	0.00	0.00	-
58	1		*FRT DOOR INNER HANDLE(LH) <i>?</i>	0.00	0.00	-
59	1		*FRT DOOR SWITCH(LH) <i>ca</i>	0.00	0.00	-
60	1		*FRT DOOR GLASS(LH) <i>bu</i>	0.00	0.00	-
61	1		*FRT DOOR GLASS OUTER MOULDING(LH) <i>an</i>	0.00	0.00	-
62	1		*FRT DOOR GLASS INNER MOULDING(LH) <i>an</i>	0.00	0.00	-
63	1		*FRT DOOR GLASS RUN CHANNEL(LH) <i>an</i>	0.00	0.00	-
64	1		*FRT DOOR GLASS REGULATOR(LH) <i>?</i>	0.00	0.00	-
65	1		*FRT DOOR GLASS MOTOR(LH) <i>?</i>	0.00	0.00	-
66	1		*FRT DOOR GLASS SWITCH(LH) <i>?</i>	0.00	0.00	-
67	1		*FRT DOOR SPEAKER(LH) <i>bt</i>	0.00	0.00	-
68	1		*FRT DOOR INNER MOULDING(LH) <i>an</i>	0.00	0.00	-
69	1		*FRT DOOR REAR PILLAR(LH) <i>bt</i>	0.00	0.00	-
70	1		*FRT DOOR REAR PILLAR INNER TRIM(LH) <i>de</i>	0.00	0.00	-
71	1		*FRT WHEEL ARCH PANEL(LH) <i>bu</i>	0.00	0.00	-
72	1		*FRT SCUFF PLATE(LH) <i>de</i>	0.00	0.00	-
73	2		*FRT STEP GARNISH <i>ca</i>	0.00	0.00	-
74	1		*FRT WHEEL ARCH PROTECTOR(LH) <i>M</i>	0.00	0.00	-
75	1		*FRT DOOR(RH) <i>bu</i>	0.00	0.00	-
76	2		*FRT DOOR HINGE(RH) <i>?</i>	0.00	0.00	-
77	1		*FRT DOOR CHECKER(RH) <i>?</i>	0.00	0.00	-
78	1		*FRT DOOR LOWER SEAL(RH) <i>an</i>	0.00	0.00	-
79	1		*FRT DOOR RUBBER(RH) <i>an</i>	0.00	0.00	-
80	1		*FRT DOOR OUTER HANDLE(RH) <i>?</i>	0.00	0.00	-
81	1		*FRT DOOR TRIMBOARD(RH) <i>de</i>	0.00	0.00	-
82	1		*FRT DOOR TRIMBOARD HANDLE(RH) <i>?</i>	0.00	0.00	-
83	1		*FRT DOOR SPEAKER(RH) <i>?</i>	0.00	0.00	-
84	1		*FRT DOOR LOCK(RH) <i>an</i>	0.00	0.00	-
85	1		*FRT DOOR SWITCH(RH) <i>?</i>	0.00	0.00	-
86	1		*FRT DOOR GLASS(RH) <i>bu</i>	0.00	0.00	-
87	1		*FRT DOOR GLASS OUTER MOULDING(RH) <i>an</i>	0.00	0.00	-
88	1		*FRT DOOR GLASS INNER MOULDING(RH) <i>an</i>	0.00	0.00	-
89	1		*FRT DOOR GLASS RUN CHANNEL(RH) <i>an</i>	0.00	0.00	-
90	1		*FRT DOOR GLASS REGULATOR(RH) <i>?</i>	0.00	0.00	-
91	1		*FRT DOOR GLASS MOTOR(RH) <i>?</i>	0.00	0.00	-
92	1		*FRT DOOR GLASS SWITCH(RH) <i>?</i>	0.00	0.00	-
93	1		*FRT DOOR GLASS INNER MOULDING(RH) <i>an</i>	0.00	0.00	-
94	1		TYPO: FRT DOOR INNER MOULDING(RH)			
95	1		*FRT DASHBOARD <i>ca</i>	0.00	0.00	-
96	1		*FRT DASHBOARD SUPPORT BEAM <i>?</i>	0.00	0.00	-
97	1		*AIRCON VENT(LH) <i>?</i>	0.00	0.00	-
98	1		*AIRCON VENT CTR <i>?</i>	0.00	0.00	-
99	1		*AIRCON VENT(RH) <i>?</i>	0.00	0.00	-
100	1		*DASHBOARD TRIM(LH) <i>?</i>	0.00	0.00	-
101	1		*DASHBOARD GLOVE BOX <i>?</i>	0.00	0.00	-
102	1		*DASHBOARD ACCESSORY TRIM <i>?</i>	0.00	0.00	-
103	1		*DASHBOARD SPEEDOMETER <i>?</i>	0.00	0.00	-
			*DASHBOARD SPEEDOMETER TRIM <i>?</i>	0.00	0.00	-

o.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
104	1		*FRT STEERING WHEEL <i>cut</i>	0.00	0.00	-
105	1		*FRT STEERING AIRBAG <i>cut</i>	0.00	0.00	-
106	2		*FRT SAFETY BELT <i>cut</i>	0.00	0.00	-
107	1		*FRT CLOCK SENSOR <i>cut</i>	0.00	0.00	-
108	1		*AIRBAG ECU <i>cut</i>	0.00	0.00	-
109	1		*FRT CABIN SUPPORT BEAM <i>cut</i>	0.00	0.00	-
110	2		*FRT CABIN SUPPORT MOUNTING <i>cut</i>	0.00	0.00	-
111	2		*FRT CABIN SUPPORT BUSH <i>cut</i>	0.00	0.00	-
112	2		*BRAKE HOSE <i>cut</i>	0.00	0.00	-
113	1		*AIR RESONATOR ?	0.00	0.00	-
114	1		*AIR RESONATOR HOSE ?	0.00	0.00	-
115	1		*FRT CHASSIS BEAM <i>repair</i>	0.00	0.00	-
116	1		*AIRCON BLOWER <i>cut</i>	0.00	0.00	-
117	1		*AIRCON BLOWER OUTER TRIM ?	0.00	0.00	-
118	1		*AIRCON COOLING COIL ASSY ?	0.00	0.00	-
119	1		*AIRCON COOLING COIL OUTER TRIM ?	0.00	0.00	-
120	1		*AIRCON HEATER COIL ?	0.00	0.00	-
121	1		*WAHER TANK ?	0.00	0.00	-
122	1		*REAR WINDSCREEN RUBBER <i>cut</i>	0.00	0.00	-
123	1		*FRT TYRE 195/R15 ? 70%	0.00	0.00	-
124	1		*FRT RIM <i>cut</i>	0.00	0.00	-
125	6		*FRT WHEEL NUT <i>cut</i>	0.00	0.00	-
126	1		*FRT WHEEL BEARING ?	0.00	0.00	-
127	1		*FRT WHEEL HUB ?	0.00	0.00	-
128	1		*FRT KING PIN ?	0.00	0.00	-
129	1		*FRT SHOCKABSORBER ?	0.00	0.00	-
130	1		*RADIATOR ?	0.00	0.00	-
131	1		*RADIATOR FAN COWLING ?	0.00	0.00	-
132	1		*RADIATOR FAN BLADE ?	0.00	0.00	-
133	1		*RADIATOR FAN MOTOR ?	0.00	0.00	-
134	2		*ENGINE MOUNTING ?	0.00	0.00	-

F=Franchise part. S=SpcNett.

Total Parts (S\$)

65.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No Particulars

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO LIFT UP CABIN	New	350 500.00
2	TO KNOCK CABIN REAR PANEL, FLOOR PANEL, REAR DECK FRT PANEL, WELD, REMOVE & REPLACE ABOVE PARTS	New	1800 2000.00
3	TO REMOVE & REPLACE DOOR GLASS & MECHANISM(x2)	New	120 160.00
4	TO REMOVE & REPLACE AIRBAG	New	200 300.00
5	TO REMOVE & REPLACE DASHBOARD	New	150 200.00
6	TO REMOVE & FIX FRT WINDSCREEN	New	120.00
7	TO REMOVE & FIX SEATS	New	100 150.00
8	TO REMOVE & FIX UPHOLSTERY	New	80 100.00
9	TO WIRING	New	30.00
10	TO DIAGNOSE & RESET FAULT CODE	New	120 180.00
11	TO REMOVE & FIX FLOOR MAT	New	60 100.00
12	TO TOP UP AIRCON GAS	New	100.00
13	TO REMOVE & FIX REAR WINDSCREEN	New	60 100.00
14	TO REPAIR & REPLACE UNDERCARRIAGE	New	150? 200.00
15	TO DO WHEEL ALIGNMENT	New	60 80.00
Gross Labour Cost (\$\$)			4,420.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Paul
By 900ms68
16 days
48
25/07/23
EXCESS - 550
Revised
Revised after repair

Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	679H

Vehicle Details

Vehicle No.:	YP2085L
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Jul 2023
Vehicle Make:	ISUZU
Vehicle Model:	NHR85AUE4A R1
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	4JJ12F3756
Chassis No.:	JAANHR85EF7100439
Maximum Power Output:	-
Open Market Value:	\$26,867.00
Original Registration Date:	11 Apr 2016
First Registration Date:	11 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$1,344.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	10 Apr 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$4,885.00
COE Rebate Amount:	\$1,331.00
Total Rebate Amount:	\$1,331.00

The information contained herein is correct as at 12 Jul 2023

OK

Isuzu NHR85A

\$39,999 Instalment \$1,193/mth

♡ Shortlist

📄 Loan Calculator



Overview Financial Photo Research

Depreciation ⓘ \$14,530 / year

Reg. Date 27-Apr-2016
(2yrs 9mths COE left)

Lifespan ⓘ 26-Apr-2036

Manufactured ⓘ 2016

Mileage -

Transmission Manual

Engine Cap 2,999 cc

Curb Weight ⓘ 1,860 kg

Fuel Type Diesel

COE ⓘ \$43,002

OMV ⓘ \$24,389

ARF ⓘ \$1,220

Dereg Value ⓘ \$11,840 as of today

No. of Owners ⓘ 1

Type of Veh **Truck**