

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Alfred Toh

Date: 26 Jul 2023

**Preliminary Advice**

Vehicle No	: YP2085L	Accident Date	: 08/07/2023
Make	: ISUZU NHR85AUE4A	Policy No.	: DMCVSNW00023062301
Assignment Date	: 25/07/2023	Excess	: S\$550.00
Date of Inspection	: 28/07/2023	Est. Duration of Repair	: 16
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

RePAIRER'S Estimate (Gross)	:S\$	4,485.00 (SN+LABOUR ONLY)
Revised Amount	:S\$	3,415.00
Check Items (Estimated)	:S\$	300.00
Total	:S\$	3,715.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	39,000.00
COE / PARF Rebate	:S\$	1,331.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,669.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : PENDING FOR PARTS PRICES FROM REPAIRER.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.