

Date: 24/07/2023

Vehicle No: SLX4722E

Model: BMW 420I GRAN COUPE

Chassis: WBA4H320X0BH13145-2018

Reg. Year: 2018

Third Party Insurer: INDIA

Third Party Veh No: SMK289Y

Date of Accident: 19/07/2023

Estimator:

Surveyor:

TING AN

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1	Bull/W	\$1,150.00
2	REAR BUMPER REINFORCEMENT	1		R \$430.00
3	REAR BUMPER REFLECTOR RH	1		CM \$50.00
4	REAR BUMPER GARNISH TRIM	1		RM \$120.00
5	REAR BUMPER SIDE RETAINER RH	1		RM \$205.00
SUB TOTAL				\$1,955.00
COST +10%				\$195.50
PARTS TOTAL				\$2,150.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		RM \$50.00
S/N TOTAL				\$50.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

2201
\$300.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER & ETC.

2201
\$300.00

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 201

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Branch

LABOUR TOTAL \$720.00

TOTAL \$2,920.50

TING AN

Head office

5 Kung Chong Road Singapore 159143

Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

9A Serangoon North Ave 5 Singapore 554600

Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047

Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

