

ASS. REC. BY:

REF:

AUS/23007518/Kgp3

6

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Add Fee:

: Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

MEN-TP

8300

Lian Her Motors

Blk 5038 #01-405 Ang Mo Kio Industrial Pk 2 Singapore 569541
Tel : 64817221

L H Car Rental Pte Ltd
Blk 5038 #01-405
Ang Mo Kio Industrial Pk 2
Singapore 569541

Vehicle No : SLS 4117 D
Make : Toyota C-HR
Year : 2017

Not within
11 days @ 8300/-
Paying After Repair
6 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Front n/s fender 645-10	By	\$855.60	✓
1 pc	Front n/s fender innershield	Sn	\$187.20	X
1 pc	Front n/s fender arch garnish	Gr	\$185.70	✓
1 pc	Front n/s fender emblem	Ma	\$55.70	✓
1 pc	Front top bumper	Sn	\$755.60	X
1 pc	Front lower bumper	Sn	\$557.60	X
1 pc	Front n/s bumper side retainer	Sn	\$75.10	X
1 pc	Front n/s door assy	At/warp	\$1,450.70	✓
1 pc	Front n/s door outer protector 366-80	mi	\$425.60	✓
1 pc	Front n/s door frame black sticker	Ma	\$85.10	✓
1 pc	Front n/s door rubber	Sn	\$197.20	X
1 pc	Front n/s door inner trim board	Sn	\$550.10	X
1 pc	Front n/s door glass regulator	Di	\$255.60	✓
1 pc	Front n/s door glass power window motor 585	Ma	\$425.60	✓
1 pc	Front n/s door side view mirror 1280-10	CM	\$1,546.70	✓
1 pc	Front n/s door side view mirror cover	mi	\$95.10	✓
1 pc	Rear n/s door	At/warp	\$1,487.60	✓
1 pc	Rear n/s door outer protector 342	mi	\$405.10	✓
1 pc	Rear n/s door inner trim board	Sn	\$540.70	X
1 pc	Rear n/s door rubber	Sn	\$185.60	X
1 pc	Rear n/s door regulator	Di	\$235.10	✓
1 pc	Rear n/s door regulator motor	Ma	\$425.60	✓
1 pc	Rear n/s door frame black sticker	Ma	\$85.10	✓
1 pc	N/S rocker panel garnish	Gr	\$647.60	✓
1 pc	Front n/s shock absorber	By	\$455.60	✓
1 pc	Front n/s linkage	Sn	\$125.60	X
1 pc	Front n/s lower arm	Sn	\$635.70	X
1 pc	Front n/s kunckle arm	By	\$550.30	✓
1 pc	Front n/s kunckle arm bearing 350	Ma	\$195.70	✓
1 pc	Front n/s hub	By	\$487.20	✓
			balance c/f	\$14,166.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SLS 4117 D

1 pc	Rear n/s shock absorber
1 pc	Rear n/s lower arm
1 pc	Rear n/s trailing arm
1 pc	Rear n/s knuckle arm

balance b/f \$14,166.70

<i>PL</i>	\$425.60	<i>X</i>
<i>PL</i>	\$497.20	<i>X</i>
<i>PL</i>	\$287.60	<i>X</i>
<i>PL</i>	\$558.20	<i>X</i>

\$14,293.50Less 25 % \$3,573.38\$10,720.12S Nett

2 pcs	Front & rear n/s tyre rim
2 pcs	Front & rear n/s door sticker

<i>PL</i>	\$450.00	\$900.00	<i>✓</i>
<i>PL</i>		\$200.00	<i>16012</i>
		<u>\$1,100.00</u>	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

0801
\$1,400.00

To putty & spray paint on accident affected portion.

0801
\$1,400.00

Check/reconnect wiring.

201
\$45.00

To spray anti rust on accident affected portion.

901
\$180.00

Remove/refit both front & rear n/s door mechanism, glass to new door

1201
\$200.00

Remove/renew front & rear n/s undercarriages

2801
\$480.00

Check and realign wheel alignment

601
\$80.00Total \$15,605.12